



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON
Governor
Betty Rivera
Cabinet Secretary

Lori Wrotenbery
Director
Oil Conservation Division

*North of Roswell
Completed
6-20-03*

Yates Petroleum Corporation
105 South 4th Street
Artesia, New Mexico 88210

Form C-103 Report of Plugging for your *Dec 04 St. #4 Sec 32-T5S-R25E 30-005-461415*
Cannot be approved until an NMOC representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- P/A*
- Location OK for Release*
- 7/9/03*
- ☒ 1. All pits have been filled and leveled.
 - ☒ 2. Rat hole and cellar have been filled and leveled.
 - ☒ 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
 - ☒ 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
 - ☒ 5. The dead men and tie downs have been cut and removed.
 - ☒ 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
 - ☒ 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Jim Ky

Name

Dir. Supr.

Title

Date:
6-30-2003

Van Barton
Field Rep. II

2nd List: -

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-60951
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

Oil Well ☐ Gas Well ☐ Other Plug & Abandon ☐

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter I : 1980 feet from the South line and 710 feet from the East line

Section 18 Township 6S Range 24E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3951' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

5-23-2003 - Moved in and rigged up pulling unit. Dug pit. Shut down for night.

5-24-27-2003 - Bled well down. Nippled down wellhead and nipped up BOP. Rigged up tubing equipment and floor. POOH with tubing. RIH with tubing ~~set CIBP~~ and set CIBP at 3100'. Circulated hole with plugging mud. Shut well in for night.

5-28-2003 - Spotted 5 sacks Class C Neat cement on top of CIBP from 3100-3028'. Pulled up hole to 1859'. Spotted 35 sacks Class C Neat cement from 1859-1353'. POOH. WOC 4 hours. RIH with tubing and tag cement at 1389'. Pulled up hole to 621'. Shut down for night.

5-29-2003 - Rigged down tubing equipment. Nippled down BOP. Rigged up tubing equipment. RIH open ended to 621'. Circulated 50 sacks Class C Neat cement from 621' to surface. POOH. WOC 4 hours. Topped off well with 5 sacks Class C Neat cement. Hole stayed full. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 5-28-2003.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina Huerta TITLE Reg. Compliance Supervisor DATE June 11, 2003

Type or print name Tina Huerta Telephone No. (505) 748-1471

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE JUL 10 2003

Conditions of approval, if any: