RECEIVED		
	New Mexico	Form C-103
District I JAN 2 2 2 1 1 1 1 2 2 2 2 2 1 1 1 2 2 2 3 2 3	and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-015-23398
811 S. First St., Artesia, NOISTRICT II-ARTESIA O.C.DONSER	VATION DIVISION	5. Indicate Type of Lease
District III 1220 Sout	n St. Francis Dr.	STATE 🗌 FEE 🛛
District IV Santa F	e, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Jackson Estate BY
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well Gas Well Other		12
2. Name of Operator EOG Y Resources, Inc.		9. OGRID Number 025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210		Eagle Creek; San Andres
4. Well Location		
Unit Letter <u>L</u> : <u>1650</u> feet from the <u>South</u> line and <u>430</u> feet from the <u>West</u> line		
Section 22 Township	17S Range 25E	NMPM Eddy County
11. Elevation (Show w	hether DR, RKB, RT, GR, etc.)	
3546' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		LING OPNS. P AND A
PULL OR ALTER CASING   MULTIPLE COMPL	☐ CASING/CEMENT	JOB 🗆
OTHER:		
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPEDATOR NAME I FACE NAME WELL NUMBER ADIMUMBER QUARTER/QUARTER LOCATION OR		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location. Casing Must Be Cut 3' BGL See CoAs)  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)  All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines. No, active pipeline(s) within EOG Y Resources gas system.		
If this is a one-well lease or last remaining well on lease		l lines have been removed from lease and well
location, except for utility's distribution infrastructure. CVE When all work has been completed, return this form to the ap		odula an increation
when an work has been completed, return this form to the ap	propriate District office to sen	dule all hispection.
SIGNATURE .	TITLE: <u>Environmental Sur</u>	pervisor DATE 1/21/2019
TYPE OF PRINT NAME: Pakes A. I	P.MAII. Dalam A.I. O	DUONIE, CCC CAO ACAC
TYPE OR PRINT NAME: Robert Asher For State Use Only		ogresources.com PHONE: 575-748-4217
	DEME	•
APPROVED BY: DENIED:	_TITLE	DATE /-23-/9
Conditions of Approval (if any):		