Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.

Э.		118	108			
	101	 		 		_

abandoned we	6. If Indian, Allottee or Tibe Name						
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No. NMNM138618						
Type of Well Oil Well		8. Well Name and No. HH SO 8 P2 6H					
2. Name of Operator CHEVRON USA INCORPORA	Contact: ATED E-Mail: LBECERR	LAURA BECERRA A@CHEVRON.COM		9. API Well No. 30-015-43934-00-X1			
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		3b. Phone No. (include an Ph: 432-687-7655	ea code)	10. Field and Pool or Exploratory Area WILDCAT			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	Confidence	_ B M-10 m 7	11. County or Parish, S	tate		
Sec 17 T26S R27E NWNW 28	30FNL 960FWL		ad Field CD Arte	11. County or Parish, S PARISH COUNTY	, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICATE NAT	JRE OF NOTICE	, REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION							
☐ Notice of Intent	☐ Acidize	Deepen	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off		
_	☐ Alter Casing	Hydraulic Frac	turing 🔲 Reclan	nation	■ Well Integrity		
Subsequent Report	□ Casing Repair	■ New Construct	ion 🔲 Recom	plete	Other		
☐ Final Abandonment Notice	□ Change Plans	Plug and Aban	don 🔲 Tempo	rarily Abandon	Drilling Operations		
	□ Convert to Injection	□ Plug Back	■ Water	Disposal			
testing has been completed. Final Abdetermined that the site is ready for fine our discussion with Zota S At the request of BLM, Chevro throughout the life of the well a	nal inspection. Stevens, attached is a sun on will continue to monitor and will bleed down the w	nmary of the recent act the pressure on the in ell as necessary.	ivities on this well	RE	CEIVED 6 2018		
A	C _ //- 7 -/ accepted for record - N		DISTRICT II-ARTESIA O.C.D.				
14. I hereby certify that the foregoing is	Electronic Submission #	SA INCORPORATED. s	ent to the Carlsbac	1			
Name (Printed/Typed) LAURA BE			·				
Signature (Electronic S	ubmission)	Date 1	0/16/2018				
	THIS SPACE FO	R FEDERAL OR \$1	ATE OFFICE U	SE			
Approved By ACCEPT	ED		A STEVENS ROLEUM ENGIN	EER	Date 10/29/2018		
Approved By ACCEPT Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive the second of the second	Approval of this notice does itable title to those rights in the ct operations thereon.	not warrant or subject lease Office C	ROLEUM ENGIN				

HH SO 8 P2 6H - API: 30-015-43934

10/12/2018 - Verify current pressure on well. FTP is 1350 #, production casing showing 0#, surface casing showing 0#, intermediate casing showing 1400#.

Bleed off pressure on intermediate casing and recovered ~16 Ozs of fluid.

Test lines and begin pumping down intermediate casing riser, pressure climbed immediately to 4000# and got 1/10th bbl into csg after 5 min.

After 9 min, approx. 2/10 bbl cumulative volume was pumped into csg while holding 4000 #. After 14 min, approx. 3/10 bbl cumulative volume was pumped into csg while holding 4000 #. Shut down pumps, pressure bleeds down to 2860# quickly, 2754 # after 10 min, 2711 # after 20 min. Bleed down rest of pressure and rig down equipment.

Chevron will continue to monitor the pressure on the intermediate casing throughout the life of the well and will bleed down the well as necessary.