State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor **Sarah Cottrell Propst** Gabriel Wade, Acting Director Cabinet Secretary Designate Oil Conservation Division Todd E. Leahy, JD, PhD **Deputy Secretary** Date: _3 -19 19 API# 30-015-229 A Mechanical Integrity Test (M.I.T.) was performed on, Well Eas M.I.T. is successful, the original chart has been retained by the Operator on site. Send a legible scan of the chart with an attached Original C-103 Form indicating reason for the test, via post mail to District NMOCD field office. A scanned image will appear online via NMOCD website, www.emnrd.state.nm.us/ocd/OCDOnline.htm 7 to 10 days after postdating. M.I.T. is unsuccessful, the original chart is returned to the Operator. Repairs will be made, Operator is to schedule for a re-test within a 90-day period. If this is a test of a repaired well currently in non-compliance, all dates and requirements of the original are still in effect. No expectation of extension should be construed because of this test. M.I.T. for Temporary Abandonment, shall include a detailed description on Form C-103, including the location of the CIBP and any other tubular goods in the well including the Operator's request for TA status timeline. M.I.T. is successful, after the secondary request of a scheduled M.I.T. is performed. Therefore, Operator has within a 30-day period from the M.I.T. to submit a current C-103 along with a legible scan of the Chart, including a detailed description of the repair(s). Only after receipt of the C-103 will the noncompliance be closed. M.I.T.is successful, Initial of an injection well, you must submit a form C-103 to NMOCD within

Please contact **Rusty Klein** at **575-748-1283 x109** for verification to ensure documentation requirements are in place prior to injection process.

30 days. A **C-103 form** must include a detailed description of the work performed on this well including the position of the packer, tubing information, the date of first injection, the tubing pressure and

If I can be of additional assistance, please feel free to contact me at (575) 748-1283 ext.

Dan Smolik, Compliance Officer EMNRD-O.C.D.

District II - Artesia, NM

Injection volume.

Thank You,