

District 2-Artesia Field Office
811 S. 1st Street
Artesia, NM 88210
(Office) 575-748-1283
(Fax) 575-748-9720
Submit 1 Copy

State of New Mexico
EMNRD-OIL CONSERVATION DIVISION

BRADENHEAD TEST REPORT

Operator Name Mesquite SWD, Inc.	³⁰ API Number 30-015-05819
Property Name Big Eddy SWD	Well No. 1

7. Surface Location

UL - Lot P	Section 3	Township 20S	Range 31E	Feet from 660	N/S Line S	Feet From 660	E/W Line E	County Eddy
------------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	----------------

Well Status

TA'D Well YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR INJ ☐ SWD ☒	PRODUCER OIL ☐ GAS ☐	DATE 6/4/2019
--	--	--	---	------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure					
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _____
Surges	Y / N	Y / N	Y / N	Y / N	GAS _____
Down to nothing	Y / N	Y / N	Y / N	Y / N	If applicable type
Gas or Oil	Y / N	Y / N	Y / N	Y / N	fluid injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Print name: Rusty Parker	Recorded online:
Title: Accepted for record - NMOCD DS 6-19-19	Re-test:
E-mail Address:	Phone #:
Date:	Witness: