

District I  
1625 N. French Dr., Hobbs, NM 88240

Energy, Minerals and Natural Resources

Revised November 3, 2011

District II  
811 S. First St., Artesia, NM 88210

OIL CONSERVATION DIVISION

District III  
1000 Rio Brazos Rd., Aztec, NM 87410

AUG 16 2019 1220 South St. Francis Dr.

Santa Fe, NM 87505

District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

DISTRICT VII-ARTESIA O.C.D.

WELL API NO. 30-015-10797
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1266
7. Lease Name or Unit Agreement Name GJ West Coop Unit
8. Well Number 23
9. OGRID Number 229137
10. Pool name or Wildcat Grayburg-Jackson

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  Oil Well  Gas Well  Other

2. Name of Operator  
COG Operating LLC

3. Address of Operator  
2208 W Main Artesia NM 88210

4. Well Location  
Unit Letter O 1980 feet from the East line and 660 feet from the South line  
Section 21 Township 17S Range 29E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3554' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER:
- PLUG AND ABANDON
- CHANGE PLANS
- MULTIPLE COMPL

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING/CEMENT JOB
- ALTERING CASING
- P AND A


Location is ready for OCD inspection after P&A

- All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
- Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
- A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. *Power Poles/Lines Not Removed*
- Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
- If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. *Buried Power Lines Not Removed*
- All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) *Flow Lines Not Removed*
- All other environmental concerns have been addressed as per OCD rules.
- Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
- If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE  TITLE Regulatory Technician

DATE 8/13/19

TYPE OR PRINT NAME Delilah Flores  
For State Use Only

E-MAIL: [dflores2@concho.com](mailto:dflores2@concho.com)

PHONE: 575-748-6946

GC

APPROVED BY: **DENIED** TITLE **DENIED**

DATE 8/20/19

Conditions of Approval (if any):