Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-015-28471
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec. NM 87410	1220 South St. Francis Dr.	STATE ☐ FEDERAL ⊠
<u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name West Red Lake Unit
PROPOSALS.)	Cas Wall Other Injection	8. Well Number 47
1. Type of Well: Oil Well 2. Name of Operator	Gas Well Other Injection	9. OGRID Number 277558
Lime Rock Resources II-A, L.P	· •	3. Odki z Mainoci 277330
3. Address of Operator		10. Pool name or Wildcat
1111 Bagby Street, Suite 4600 F	Houston, Texas 77002	Redlake: Queen-Grayburg-SA
4. Well Location		
Unit Letter G		1510 feet from the East line
Section 08		NMPM NM County Eddy
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 3475' GL	
品。在15年12日的15年2月2日 2月1日 2月1日 2月1日 2月1日 2月1日 2月1日 2月1日	· · · · · · · · · · · · · · · · · · ·	a succession of the succession
12 Check	Appropriate Box to Indicate Nature of Notice	Report or Other Data
	•	, Report of Other Data
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS COMMENCE DF MULTIPLE COMPL CASING/CEMEN	RILLING OPNS. P AND A
DOWNHOLE COMMINGLE	CASING/CEME	11 100
CLOSED-LOOP SYSTEM		
OTHER:	OTHER: Corre	ective Actions (Violation)
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or re	completion.	Simpletions. Attach wellbore diagram of
,	,	
API Number has been place	ed on well sign.	
		AUG 1 4 2019
		DISTRICTII-ARTESIAO.C
		DIZIUM MAGAM 1210
•		•
		•
Spud Date:	Rig Release Date:	
I hereby certify that the information	above is true and complete to the best of my knowled	ge and belief.
, ~ / /	7	
SIGNATURE MA	TITLE Production Superintende	ent DATE 08-7-19
	<u> </u>	
Type or print name <u>Michael Barr</u>		kresources.com PHONE: <u>575-365-9724</u>
APPROVED BY: De Conditions of Approval (if any):	TITLE Compliance	DATE 8-14-19

State Of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham

Governor

Sarah Cottrell Propst

Cabinet Secretary

Todd E. Leahy, JD, PhD

Deputy Cabinet Secretary

Adrienne Sandoval

Division Director

"Response Required - Deadline Enclosed"

Field Inspection Program "Preserving the Integrity of Our Environment"



01-Aug-19

LIME ROCK RESOURCES II-A, L.P.

Suite 4600 Houston, TX 77002

Dear Operator:

LETTER OF VIOLATION - Field Inspection 1111 Bagby Street

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-015-28471] WEST RED LAKE UNIT #047

OGRID: 277558

G-08-18S-27E 2310 FNL 1510 FEL

Inspection Date

Type Inspection

Inspector

Corrective Action Due By

Inspection No.

8/1/2019

Routine Inspection

[DRS] Danny Smolik

10/30/2019

iDRS1921330178

Violations:

Rule

Violation

19.15.16.8 Sign on Wells

Inaccurate Information

Comment:

No API number on sign sign

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By." date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.