

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-28940
5. Indicate Type of Lease STATE <input type="checkbox"/> FEDERAL <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name West Red Lake Unit
8. Well Number 71
9. OGRID Number 277558
10. Pool name or Wildcat Redlake: Queen-Grayburg-SA

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Injection

2. Name of Operator  
Lime Rock Resources II-A, L.P.

3. Address of Operator  
1111 Bagby Street, Suite 4600 Houston, Texas 77002

4. Well Location  
Unit Letter B : 710 feet from the North line and 1650 feet from the East line  
Section 08 Township 18S Range 27E NMPM NM County Eddy

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3422' GL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: Corrective Actions (Violation) ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

API Number has been placed on well sign.

RECEIVED

AUG 14 2019

DISTRICT II-ARTESIA O.C.D.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael Barrett TITLE Production Superintendent DATE 08-7-19

Type or print name Michael Barrett E-mail address: mbarrett@limerockresources.com PHONE: 575-365-9724

APPROVED BY Daniel TITLE Compliance Officer DATE 8-14-19

Conditions of Approval (if any):


RECEIVED AUG 06 2019

# State Of New Mexico

## Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham  
Governor  
Sarah Cottrell Propst  
Cabinet Secretary  
Todd E. Leahy, JD, PhD  
Deputy Cabinet Secretary

Adrienne Sandoval  
Division Director



### "Response Required - Deadline Enclosed"

*Field Inspection Program  
"Preserving the Integrity of Our Environment"*

01-Aug-19

**LIME ROCK RESOURCES II-A, L.P.**  
1111 Bagby Street  
Suite 4600  
Houston, TX 77002

### LETTER OF VIOLATION - Field Inspection

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

### INSPECTION DETAIL SECTION

[30-015-28940] WEST RED LAKE UNIT #071

OGRID: 277558

B-08-18S-27E 710 FNL 1650 FEL

Inspection Date	Type Inspection	Inspector	Corrective Action Due By	Inspection No.
8/1/2019	Routine Inspection	[DRS] Danny Smolik	10/30/2019	iDRS1921326349

**Violations:**

Rule	Violation
19.15.16.8 Sign on Wells	Inaccurate Information

**Comment:**

No API number on sign

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division \* 811 S. First St. \* Artesia, NM 88210  
Phone: 575-748-1283 \* Fax: 575-748-9720 \* www.emnrd.state.nm.us