

UNITED STATES **Carlsbad Field Office**  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB NO. 1004-0137  
Expires: January 31, 2018

**SUNDRY NOTICES AND REPORTS ON WELLS**  
**OCD Artesia**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*

|  |
|--|
| 5. Lease Serial No.<br>NMLC028793A                                     |
| 6. If Indian, Allottee or Tribe Name                                   |
| 7. If Unit or CA/Agreement, Name and/or No.<br>NMNM88525X              |
| 8. Well Name and No.<br>BURCH KEELY UNIT 965H                          |
| 9. API Well No.<br>30-015-40973-00-S1                                  |
| 10. Field and Pool or Exploratory Area<br>BURCH KEELY-GLORIETA-UPR YES |
| 11. County or Parish, State<br>EDDY COUNTY, NM                         |

**SUBMIT IN TRIPLICATE - Other instructions on page 2**

|  |   |
|--|---|
| 1. Type of Well<br><input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other |   |
| 2. Name of Operator<br>COG OPERATING LLC<br>Contact: DANA KING<br>E-Mail: dking@concho.com                                       |   |
| 3a. Address<br>600 W ILLINOIS AVENUE<br>MIDLAND, TX 79701  | 3b. Phone No. (include area code)<br>Ph: 432-818-2267 |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)<br>Sec 19 T17S R30E SENE 2350FNL 493FEL                   |   |

**12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

| TYPE OF SUBMISSION                                    | TYPE OF ACTION                                |   |  |  |
|---|---|---|--|--|
| <input type="checkbox"/> Notice of Intent             | <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen               | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off                          |
| <input checked="" type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Hydraulic Fracturing | <input type="checkbox"/> Reclamation               | <input type="checkbox"/> Well Integrity                          |
| <input type="checkbox"/> Final Abandonment Notice     | <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction     | <input type="checkbox"/> Recomplete                | <input checked="" type="checkbox"/> Other Venting and/or Flaring |
|   | <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon     | <input type="checkbox"/> Temporarily Abandon       |  |
|   | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back            | <input type="checkbox"/> Water Disposal            |  |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BURCH KEELY UNIT 19A BATTERY

PERMIT APPROVAL: EC #460410

ACTUAL GAS FLARED FOR THIS BATTERY FOR 4/4/2019 - 7/3/2019 IS AS FOLLOWS:

APRIL  
TOTAL FOR BATTERY = 0

MAY  
TOTAL FOR BATTERY = 0

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

Accepted for record OCT 07 2019  
NMOCD  
10/31/19  
RECEIVED

|  |                          |
|--|--------------------------|
| 14. I hereby certify that the foregoing is true and correct.<br><b>Electronic Submission #486070 verified by the BLM Well Information System</b><br><b>For COG OPERATING LLC, sent to the Carlsbad</b><br><b>Committed to AFMSS for processing by PRISCILLA PEREZ on 10/03/2019 (20PP0047SE)</b> |                          |
| Name (Printed/Typed) DANA KING   | Title SUBMITTING CONTACT |
| Signature (Electronic Submission)  | Date 10/01/2019          |

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

|   |  |                         |
|---|--|-------------------------|
| Approved By _____   | Title <b>Accepted for Record</b>                               | Date <b>OCT 03 2019</b> |
| Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. | Office <b>Jonathon Shepard</b><br><b>Carlsbad Field Office</b> |                         |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\***

**Additional data for EC transaction #486070 that would not fit on the form**

**32. Additional remarks, continued**

JUNE  
TOTAL FOR BATTERY = 0

JULY  
TOTAL FOR BATTERY = 0

NUMBER OF WELLS TO FLARE: 12

BURCH-KEELY UNIT #238 30-015-28331  
BURCH-KEELY UNIT #418 30-015-36183  
BURCH-KEELY UNIT #626 30-015-40276  
BURCH-KEELY UNIT #643 30-015-39570  
BURCH-KEELY UNIT #644 30-015-39571  
BURCH-KEELY UNIT #651 30-015-40278  
BURCH-KEELY UNIT #654 30-015-40280  
BURCH-KEELY UNIT #656 30-015-40005  
BURCH-KEELY UNIT #657 30-015-39567  
BURCH-KEELY UNIT #914 30-015-40300  
BURCH-KEELY UNIT #964H 30-015-44149  
BURCH-KEELY UNIT #965H 30-015-40973

FROM: 4/04/2019 THROUGH 7/03/2019

150 BOPD  
650 MCFD

REASON: UNPLANNED MIDSTREAM CURTAILMENT DUE TO PLANT MAINTENANCE OR HLP.