

Submit One Copy To Appropriate District O 2 State of New Mexico Office	Form C-103
Submit One Copy To Appropriate District State of New Mexico Office District 1 1625 N. French Dr., Hobbs, NM 88340 OIL CONSERVATION DIV. 811 S. First St., Artesia, NM 88210	esources Revised November 3, 2011 WELL API NO.
District II  811 S. First St. Artesia, NM 88210  OIL CONSERVATION DIV	ISION 30-005-64068
District III 1220 South St. Francis D	or.   5. Indicate Type of Lease   STATE   FEE   □
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. LG-155
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUC	CK TO A WILLOW CREEK BFI STATE
PROPOSALS.)  1. Type of Well: □Oil Well ☑ Gas Well □ Other	8. Well Number 9
2. Name of Operator VANGUARD OPERATING LLC	9. OGRID Number
3. Address of Operator 5847 SAN FELIPE ST SUITE 3000 HOUSTON, TX 77057	10. Pool name or Wildcat PECOS SLOPE; ABO
4. Well Location	
Unit Letter $E: 2310$ feet from the NORTH line and 800 feet from the WEST line	
Section 30 Township 4S Range 25E NMPM County CHAVES	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3941' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REM	SUBSEQUENT REPORT OF:  IEDIAL WORK ALTERING CASING
	MMENCE DRILLING OPNS. P AND A
<del>-</del>	ING/CEMENT JOB
	out to the second of a COD in a section of an DOA
OTHER:    Description   Descri	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
ODED ATOD NAME A DACE NAME WELL NUMBED ADIMIMPED OHADTED/OHADTED LOCATION OF	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. The hand so the first share been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and p	pit location(s) have been remediated in compliance with
OCD rules and the terms of the Operator's pit permit and closure plan. All flo	w lines, production equipment and junk have been removed
from lease and well location.	have a war and (Dayred analta concrete have do not have
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
to be removed.) Flow Line Rieces on Road to location Not Removed.  Mail other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.  If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	
location, except for utility 3 distribution inhabitated.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE (1/26/19	
TYPE OR PRINT NAME C.M. BLOODWORTH, P.E. E-MAIL: mbloodworth@vnrenergy.com PHONE: 432-770-9738	
	_ mais = 1
wesive a	DENIED GC DATE / 2/3/19
APPROVED BY: TITLE  Conditions of Approval (if any):	DENIED GC.  DATE / 2/3/19