Submit One Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Minerals and Natural Resources	Revised November 3, 2011
1025 N. 11chen Dr., 110008, NW 68240		WEEL ATTNO.
District II 811 S. First St., Artesia, NM 88210	QIL CONSERVATION DIVISION	30-015-37423
District III DEC 1	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe NM 87505	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe. NSTRICTION 87505	RIESIAO: C. I VIVI 67303	6. State Oil & Gas Lease No.
87505 DISITIO 11.15		
SUNDKI NOTICES A	IND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		SRO STATE UNIT
PROPOSALS.)	, (FORM C-101) FOR SOCH	8. Well Number
1. Type of Well: Oil Well Gas W	Vell Other	015H
2. Name of Operator		9. OGRID Number
COG Operating LLC		229137
3. Address of Operator		10. Pool name or Wildcat
2208 W Main Artesia NM 88210		HAY HOLLOW, BONE SPRING
4. Well Location		
Unit Letter D: 660 feet from the 1	North line and 330 feet from the West line	·
Section 17 Township 26S R	Range 28E NMPM Eddy County	•
	Elevation (Show whether DR, RKB, RT, GR,	etc.)
3,122' GR		
12. Check Appropriate Box to Indic	cate Nature of Notice, Report or Othe	er Data
	-	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		
PULL OR ALTER CASING MUL	TIPLE COMPL	MENT JOB
OTHER:	. □ ⊠ Location	is made for OCD in an action of an DOA
OTHER:		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
		are in concrete. At one include
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED O	ON THE MARKER'S SURFACE.	
	y as possible to original ground contour and	has been cleared of all junk, trash, flow lines and
ather production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location was 1111 The hand the wines, production equipment and junk have been removed		
from lease and well location. Well Info on Marker with the location with the locatio		
to be removed.) All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
		s and lines have been removed from lease and well
location, except for utility's distribution inf	rastructure.	• 4
777		
	discount of the province of	
when all work has been completed, return t	this form to the appropriate District office to	schedule an inspection.
when all work has been completed, return t	this form to the appropriate District office to	schedule an inspection.
SIGNATURE SIGNATURE	this form to the appropriate District office to TITLE Regulatory Techn	•
SIGNATURE		•
SIGNATURE TYPE OR PRINT NAME Delilah Flores		•
SIGNATURE	TITLE Regulatory Techn	ician DATE 12/9/2019 PHONE: 575-748-6946
TYPE OR PRINT NAME Delilah Flores For State Use Only	TITLE Regulatory Techn. E-MAIL: dflores2@concho.com	ician DATE 12/9/2019 PHONE: 575-748-6946
SIGNATURE TYPE OR PRINT NAME Delilah Flores	TITLE Regulatory Techn	ician DATE 12/9/2019 PHONE: 575-748-6946