



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

Field Inspection Program

"To preserve the integrity of New Mexico's oil and gas resources"

07-Jul-03

M E W ENTERPRISES

300 S. KENTUCKY AVE

ROSWELL, NM 88203-4523

NOTICE OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

CANNON FEE 002Y

A-17-10S-25E

30-005-61234-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2003	Compliance Verification	Mike Bratcher	Yes	No	8/4/03	iMLB0318442737

Comments on Inspection: New well sign installed on pumpjack. Closed violation compliance module. Valve at wellhead has been left open allowing oil to pool and run out onto location. Violation Rule 13 and Rule 116.

CANNON FEE 003

H-17-10S-25E


30-005-61499-00-00

Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
07/03/2003	Compliance Verification	Mike Bratcher	Yes	No	8/4/2003	iMLB0318440630

Comments on Inspection: New well sign lists well name as Mary Cannon # 2 and footages as 1650s 330e. OCD records indicate well is Cannon # 3 and footages are 1650n 356e. Sign is still in violation of Rule 103.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

Note: nformation in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.