RECEIVED

Submit One Copy To Appropriate District Office JAN 1 3 2020 State of New Mexico Energy, Minerals and Natural Resourc	Form C-103 es Revised November 3, 2011
District II 811 S. First St., Artesia, NM 88210 District III 812 S. First St., Artesia, NM 88210 District III 1220 Street III	WELL API NO. 30-005-63538
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410	5. Indicate Type of Lease STATE FEE
District IV Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	VA-2101
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Miller State
1. Type of Well: ☑Oil Well ☐ Gas Well ☐ Other	8. Well Number #1
Name of Operator Hanson Operating Company, Inc.	9. OGRID Number 009974
3. Address of Operator P O Box 1515, Roswell, New Mexico 88202-1515	10. Pool name or Wildcat 00800 Acme San Andres, Southeas
4. Well Location	
Unit Letter N: 1200 feet from the South line and 1980 feet from Section 2 Township 8 South Range 27 East NMPM Cou	
Section 2 Township 8 South Range 27 East NMPM Countries 11. Elevation (Show whether DR, RKB, RT, G 3929' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Ot	her Data
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	SUBSEQUENT REPORT OF:
	EMENT JOB
OTHER:	on is ready for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the	ne Operator's pit permit and closure plan.
Rat hole and cellar have been filled and leveled. Cathodic protection holes have A steel marker at least 4" in diameter and at least 4' above ground level has been filled and leveled.	
in diameter and at least 1 move ground level has bee	is set in concrete. It shows the
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBE UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORM	R, QUARTER/QUARTER LOCATION OR
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	TATION HAS BEEN WELDED OR
☐ The location has been leveled as nearly as possible to original ground contour a other production equipment.	nd has been cleared of all junk, trash, flow lines and
Anchors, dead men, tie downs and risers have been cut off at least two feet below	
If this is a one-well lease or last remaining well on lease, the battery and pit local	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow line from lease and well location.	s, production equipment and junk have been removed
All metal bolts and other materials have been removed. Portable bases have been to be removed.	n removed. (Poured onsite concrete bases do not have
to be removed.) All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 retrieved flow lines and pipelines.	IMAC. All fluids have been removed from non-
✓ If this is a one-well lease or last remaining well on lease: all electrical service po	oles and lines have been removed from lease and well
location, except for utility's distribution infrastructure.	n danial have been removed
The trash and plastic liner referenced in the 7/1/2019 Finalization When all work has been completed, return this form to the appropriate District office	
The riser is the property of the gas pipeline company. The pipeline	
SIGNATURE (ANN). Anth TITLE Production A	nalyst DATE 01/09/2020
TYPE OR PRINT NAME Carol J. Smith E-MAIL: hanson@c	Ifn.com PHONE: <u>575-622-7330</u>
ADDROVED DV. ALA SOLO STATE OF CO.	