

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-26821

## Release Notification and Corrective Action

nMLB06/714/695

## OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 <sup>TH</sup> Street	Telephone No. 505-748-1471	
Facility Name <i>NMMP # 100</i> Volght AJD Com. #1 & #2 Tank Battery	API Number 30-015-26821	Facility Type Battery



Surface Owner Fee	Mineral Owner Fee	Lease No.
----------------------	----------------------	-----------

## LOCATION OF RELEASE

Unit Letter D	Section 29	Township 19S	Range 25E	Feet from the 660	North/South Line North	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.63719 Longitude 104.51278

## NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 20 B/PW	Volume Recovered 17 B/PW
Source of Release Water Tank	Date and Hour of Occurrence 5/16/2006 - AM	Date and Hour of Discovery 5/16/2006 - AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Head switch on water tank failed. Picked up standing fluids with a vacuum truck.		
Describe Area Affected and Cleanup Action Taken.* An approximate area of 15' X 35', inside of berm. Repaired switch. Requesting final closure. SITE RANKING IS 10.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Approved by District Supervisor <b>TIM GUM</b> by MB 	
Title: Environmental Regulatory Agent	Approval Date: <u>6/20/06</u>	Expiration Date: <u>N/A</u>
E-mail Address: boba@ypcnm.com	Conditions of Approval: <i>Removal of Contaminated Soil &amp; stock pile</i>	Attached <input type="checkbox"/>
Date: Friday, May 26, 2006	Phone: 505-748-1471	

\* Attach Additional Sheets If Necessary