## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

QCD-ARTESI

FORM APPROVED OMB No. 1004-0135

## SUNDRY NOTICES AND REPORTS ON WELLS

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Expires January 31, 2004

5. Lease Serial No.

Do not use this form for proposals to drill or re enter an							NM-14118	
abandoned well. Use Form 3160-3 (APD) for such proposals.						6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side						7. If Unit or CA/Agreement, Name and/or No.		
Oil Well Gas Well X Other P&A JUN 2 7 200c						8. Well Name and No.		
2. Name of Operator						Allison CQ Federal #5		
Yates Petroleum Corporation						9. API Well No.		
3a. Address 3b. Phone No. (include area code)						30-015-2314	5	
105 S. 4th Str., Artesia, NM 88210 505-748-1471						10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec.,T.,R.,M., OR Survey Description)							vn	
CONTRAL O ACCOUNTANT OF CONTRACT AS TACK DOAT (Unit C. NITANAI)						11. County or Parish, State		
660'FNL & 1980'FWL of Section 13-T19S-R24E (Unit C, NENW)  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, RE						Eddy County, New Mexico		
		TATE BOX(I	ES) TO INDICA			PORT, OR OT	HER DATA	
TYPE OF SUBMISSION TYPE OF ACTION								
		Acidize		Deepen	Production	(Start/Resume)	Water Shut-Off	
Notice of Intent		Alter Ca	asing	Fracture Treat Reclamation		on Well Integrity		
	1	Casing	Repair	New Construction Recomple		Other		
Subsequent Report		Change	Plans	X Plug and Abandon Temporati		ly Abandon		
	Final Abandonment Notice	Conver	t to Injection	Plug Back	Water Disp	osal		
13. Describe Pr	J roposed of Completed Operation (				·			
6/8/06 6/9/06 6/12/06 6/13/06	at 5190'.  Squeezed 50 sx cement at 5190'. WOC 2 hrs. Tagged at 4903'. Perforated at 3904'. Squeezed 50 sx cement at 3904'. WOC 1 hr.  Tagged at 3662'. Perforated at 1800'. Squeezed 50 sx cement at 1800'. WOC 1-1/2 hrs. Tagged at 1670'. Perforated at 962'. Squeezed 50 sx cement at 962'. WOC 1-1/2 hrs. No tag. WOC 1-1/2 hrs. Squeezed 50 sx cement.  Tagged at 747'. Perforated at 413'. Squeezed 100 sx cement to surface. Circulated cement to surface. Spotted 3 sx cement at surface. Cut off wellhead and anchors. Installed dry hole marker.  WELL IS PLUGGED AND ABANDONED. FINAL REPORT.  ACCEPTED ACCEPTED							
				NMOCD/		]   JUN	2 2 2006	
Please notify Mark Hoskins (505-703-3308) 3 days prior to BLM inspection, so we have the opportunity to meet with the inspector on location to confirm all reclamation requirements before receiving the notice of written order.  PETROLEMAN								
inspector	on location to confirm	i ali reciarrial	ion requiremen	is before recei	ving the notice	PETROLI	Y GOURLEY EUM ENGINEER	
14. I hereby c	ertify that the foregoing is true	and correct		T	<del></del>			
Name	(Printed/Typed) Tina Huerta			Title Reg	gulatory Compli	ance Supervis	or	
Signature	(Sina)	Just	ta	<sub>Date</sub> Jun	e 16, 2006			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by				Title	9	Date	)	
certify that th	approval, if any, are attached the applicant holds legal or equ	itable title to thos	se rights in the subjec		ce			
	entitle the applicant to conduct			ny pareon knowingly	and willbully to make	to any department o	r agency of the United	