District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Form C-141 Revised October 10, 2003 bmit 2 Copies to appropriate

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

1220 S. St. Fran	icis Dr., Sant	a Fe, NM 8/505	,	Sa	anta F	e, NM 875	05					Side of form
30-015	-285	36	Rele	ease Notific	catio	n and Co	rrective A	ction				
n MLBO	~ 211	1115		125	~0	OPERA	TOR		[ ] Initi	al Report		Final Report
Name of Co	ompany K	err-McGee	OPERATOR ☐ Initial Report ☑ Final Report Contact Richard Schauffler									
Address P	O Box 14	78, Carlsbac	Telephone No. 281.673.6099									
		t Federal 28	Facility Typ	e Oil and Gas	Produ	ction						
Surface Ow	ner State	of NM (BL	Kerr-McGee Oil and Gas Lease No. Bright Federal 28-2									
				LOC	ATIO	N OF REI	LEASE					
Unit Letter	Letter Section Township Range Feet from the No					h/South Line   Feet from the   East/West Line				County Eddie	PE.	רשיים
	1		<u></u>	Latitude 32°	26.82	' Longitud	le <u>104° 36.58°</u>	<u> </u>		٢.		30 7006
						OF RELI						
Type of Rele	ase produ	ced water (no	condensa	ate and/or oil)	CITI		Release 15 bbls		Volume F	Recovered	ten (10	) bbls
		in SDR7 poly #3 SWD well	unknown	Date and Hour of Occurrence Date and Hour of Discovery					/			
Was Immedi	ate Notice	Given?	Yes 🔲	No 🗹 Not Re	quired	If YES, To Whom?						
By Whom?		<del></del>	Date and Hour									
Was a Water	course Rea	If YES, Volume Impacting the Watercourse.										
			Yes 🗹	] No								
If a Watercou	urse was In	pacted, Descr	ibe Fully.*	,								
No watercou	ırse or wat	ers of the stat	te or US w	vere impacted/af	fected.							
Describe Cau	ise of Prob	lem and Reme	dial Action	n Taken.*								
		_		ransfer line to Bu olve repair/repla			_		vas immed	liate to the	flowli	ne;
Describe Are	a Affected	and Cleanup A	Action Tak						-1. 1, 18. 14. 1			
		•										
thousand (2	000) squar		proximate	dine. Ten (10) b ely 0.02 inch of soil.								
regulations a public health should their of or the environ	Il operators or the envi operations l nment. In a	are required to ironment. The have failed to a	o report and acceptance acceptanc	e is true and comp ad/or file certain r ce of a C-141 repo investigate and r stance of a C-141	elease rort by the emedian	notifications ar ne NMOCD mate contaminati	nd perform correct arked as "Final R on that pose a thr	tive acti eport" d eat to gr	ons for rele oes not reli ound water	eases which ieve the ope r, surface w	n may e crator o ater, hu	endanger of liability uman health
Signature: Lilly, Solly						OIL CONSERVATION DIVISION  by MB						
Printed Name	e: Richard	P. Schauffler,	Approved by District Supervisor:						462			
Title: Superv	visor, EHS,	Southern Reg	Approval Dat	e: Who	1	Expiration	Date: 4//	, ,				
E-mail Addre	ess: <u>rschau</u>	ffler@kmg.com	Conditions of Approval: M/A									

Phone: 281.673.6099

\* Attach Additional Sheets If Necessary



JUN 3 0 2006

Richard Schauffler, REM
EHS SUPERVISOR, SOUTHERN REGION

KERR-MCGEE OIL & GAS ONSHORE LP 16666 NORTHCHASE DRIVE • HOUSTON, TX 77060 281-673-6099 • FAX 281-673-4099 E-MAIL, RSCHAUFFLER@KMG COM

June 27, 2006

New Mexico Energy Minerals and Natural Resources
Oil Conservation Division
District II
1301 West Grand Avenue
Artesia. New Mexico 88210

RE:

Spill Report

Kerr-McGee Oil and Gas Onshore LP

**Bright Federal 28-2** 

Indian Basin

Sec: 21 Twn: 21S Rng: 23E

Latitude 32° 26.82' and Longitude 104° 36.58'

**Eddie County, New Mexico** 

In accordance with New Mexico Administrative Code ("NMAC"), please find written documentation and the state required Form C-141 for a discharge which occurred at the above referenced on June 15, 2006.

30-015-28556

Approximately fifteen (15) barrels of produced water and zero (0) barrels of condensate/oil were released due to a leak in the flowline. The impacted area was immediate to the flowline and no waters of the state and/or US were affected. Ten (10) barrels of produced water were recovered. The estimated surface area impact is two-thousand (2000) square feet and approximately 0.02 inch of vertical soil impact occurred. This affected area will be fertilized and tilled to mix and promote bioremediation of the impacted soil.

Preventative action for re-occurrence will involve replacement of this section of flowline.

If you have any questions, or need additional information, please contact me at 281.673.6099.

Sincerely,

Richard P. Schauffler, REM

Kerr-McGee Oil & Gas Onshore LP EH&S Supervisor, Southern Region

enci.

Form C-141/Release Notification and Corrective Action

C:

Bureau of Land Management ("BLM")

Mr. Jim Amos 620 East Green Carlsbad, NM 88220

Stuart Wittenbach Danny Henderson

Clay Hill Bobby Hess Keith Conner Steve Brannan EHS file



SOUTHERN DIVIS				· · · · · · · · · · · · · · · · · · ·	Facility type	*	State	County		KME-10432 (01/06)	
' 1	Facility name Bright Federal 28-2 Facility				Battery		New Mexico	Eddy		Indain Basin	
Legal description			20-2 1 ac	Dattory		THEW INICATED	Incident date		Incident time		
Sec 21-T21-R23E								6/15/2006		08:00	
ncident description			······································							1,	
Leak in SDR7 poly	yline fr	om Bri	ght Federa	l transfer	line to Bunn	el #3 SW	D				
Property damage descri	ption							Date known	o K-M	Time known to K-M	
								6/15/2006		15:18	
· · · · · · · · · · · · · · · · · · ·				State repo	tate reportable			Reported to EH&S by		Date reported to EH&S	
Production-1010N	ſ			No				Bobby He	SS	6/15/2006	
Spill type			Source			1	y cause		Secondar		
Liquid			Flowline	-1020N			anical Failure-0		rom list		
Cleanup action					***************************************	ı	to prevent recurrence			HECEIV	
remediate in place						Repla	ice section of lin	ne		JUN 3 0 2	
<u> </u>			r						T 0. ""	UVUFATT	
Cleanup date Area (sq. ft			i)		0.02	of spill into ground (f	t.) Spili conti		ained inside berm		
6/16/2006 2000						name and number			amo number		
Surface owner Federal			1	Vitness Steve Brannan			2		Lease name number Bright Federal 28		
- Cuciai			Sieve Di	Steve Diaminan					Di igni i	Cucrai 20	
Product spilled		Quanti	ty spilled BLS)	Quan				Agency	n		
		(5)	——————————————————————————————————————	recovered	(DDL3)		Agency	Contac		Contact number	
Produced Water-10	020N	15		10			Agency	Contac	•	Contact number	
							Date of call	Time o	call	Employee who called	
Select from list						1				,	
~ 1	$\neg \neg$						Comments				
Select from list							}				
Media type		1	Media type addidional			<del></del>	Agency	Contac		Contact number	
Soil-1030N		S	Select from list								
lf in water, explain					2	Date of call	Time of call		Employee who called		
		·				_					
		Spill Cos	st				Comments				
KMG staff hours			iscellaneous	rnet			Agency	Contac		Contact number	
2		- 1	00				Jonac	-	SS. M. C. Hornbell		
Damages paid to owner			Total agency fines				Date of call	Time of	cail	Employee who called	
• • • • • • • • • • • • • • • • • • • •			,			3	]				
Contractor		C	ost				Comments			<del></del>	
		ļ									
Contractor		C	ost			<del></del>	Agency	Contac		Contact number	
Contractor		Co	ost			4	Date of call	Time of	call	Employee who called	
						·					
Contractor		Co	ost				Comments				
				<del> </del>		<del></del>	<u> </u>				
reparer ·						Date					
Keith Conner						1 Y	19, 2006				