

District I\*  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

30-015-30797

Release Notification and Corrective Action

NMLB0608155793

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Devon Energy Production Co. LP 6137	Contact: Jennifer Van Curen
Address: PO Box 250; Artesia, NM 88211	Telephone No.: 505-748-0160
Facility Name: W. Shugart 19 Battery	Facility Type: Battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter E	Section 19	Township 18S	Range 31E	Feet from the 2310	North/South Line NORTH	Feet from the 990	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release: WATER SPILL	Volume of Release: 15	Volume Recovered: 2
Source of Release: Hole in water leg	Date and Hour of Occurrence 10-28-05; 10:30 am	Date and Hour of Discovery 10-28-05; 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom?	Date and Hour: 10-28-05; 1:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED

If a Watercourse was Impacted, Describe Fully.\*

APR 06 2006

ODD-ANTECOM

Describe Cause of Problem and Remedial Action Taken.\*

Hole came into the water leg on heater. Leaked 15 bbls and recovered 2 bbls. Spill covered about a 100' long by 6' wide. Shut well in and drained heater, pulled water leg, and replaced water leg with fiberglass water leg.

Describe Area Affected and Cleanup Action Taken.\*

Area affected was the well pad. Left area to aerate and fertilized on 10-31-05. Will repeat the procedure as needed to reduce contamination. Spill was contained on well pad. Area is ready for final inspection.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jennifer Van Curen</i>	OIL CONSERVATION DIVISION	
Printed Name: Jennifer Van Curen	Approved by District Supervisor <i>TIM GUM</i>	BY MP <i>Mike Bratcher</i>
Title: Production Field Tech	Approval Date: <i>11/7/06</i>	Expiration Date: <i>N/A</i>
E-mail Address: Jennifer.vancuren@dv.com	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: 4-5-06	Phone: 748-0160	

\* Attach Additional Sheets If Necessary