Submit 3 Copies To Appropriate District State of New Mexico	CORRECTED Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Ave. Artesta NM 88210 OIL CONSERVATION DIVISION	30-015-24653
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505District IVSanta Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	NM-01119
SUNDRY NOTICES AND REPORTS ON WHITS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPENDER PLUG ENCK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORME-101) FOR SECH PROPOSALS.)	Avalon (Delaware) Unit
1 Type of Well Oil Well XI Gas Well Other 1. View 🕷 🗸 🗸 🗸	a ven rumber
2. Name of Operator Exxon Mobil Corporation	007673
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 4358, CORP-MI-P056, Houston, TX 77210-4358 4. Well Location	Avalon; Delaware 3715
Unit Letter 1 : 990 feet from the North line and 990	feet from theWestline
Section 30 Township 20S Range 28E	NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
3295' GR Pit or Below-grade Tank Application or Closure	
	stance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; C	Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
OTHER: OTHER: Mech	nanical Integrity Test 2 7/19 🛛
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	
11/29/06 MIRU WSU. POOH with rods and pump. NDWH, NU BOP, POOH with 61 jts 2-7/8" tbg secure well,	
SION.	
11/30/06 Roads iced over. Crew returned home. SION.	
12/01/06 RIH with gauge ring & tag @ 2616'. RIH with CIBP & set @ 2500'. RIH with 78 jts open ended tubing. Load & test tbg to 500 psi. Test good. Circulate packer fluid. Lay down 48 jts, leaving 30 jts in hole as kill string.	
SION.	
100 to	Abardoned Status approved
12/27/06 Ran MIT test. Original chart is attached.	A 18-00
Chart reflects 50# Loss	
V	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].	
SIGNATURE SIGNATURE SIGNATURE SIGNATURE	Assistant DATE 12-28-06
Type or print name E-mail address:	Telephone No.
For State Use Only Geny G	-
A PARA Deputy Eigld	
APPROVED BY:	Artesia DATE

,k

.

DEC 2 8 2006



ł

ŧ.