

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

May 27, 2004

WELL API NO.

30-015-31604

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

V-2705

7. Lease Name or Unit Agreement Name

Graham AKB State

8. Well Number

3

9. OGRID Number

025575

10. Pool name or Wildcat

Lost Tank; Delaware

SUNDRY NOTICES AND REPORTS ON WELL

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG-BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other P&A

2. Name of Operator

Yates Petroleum Corporation

3. Address of Operator

105 S. 4th Street, Artesia, NM 88210

4. Well Location

Unit Letter B : 660 feet from the North line and 1650 feet from the East line
Section 2 Township 22S Range 31E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3536'GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P & A ☒

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/26/06 – RIH with gauge ring, would not go past 5600'. Pumped fresh water. NOTE: NMOCD approved to spot 50 sx cement. RIH with tubing to 6760'. Broke circulation with plugging mud. Spotted 50 sx cement and WOC.

12/27/06 – Tagged at 5920'. Perforated at 4364'. Pumped 35 sx cement and WOC. Tagged at 4214'. Perforated at 4200'.

12/28/06 – Pumped 35 sx cement and WOC. Tagged at 4000'. Pumped 108 sx cement at 3984'. Spotted 108 sx cement at 2893'. Pumped 108 sx cement at 1800'.

1/1/07 – Tagged at 802'. Circulated 20 sx cement 163' to surface. Cut off wellhead. Installed dry hole marker. **WELL IS PLUGGED AND ABANDONED. FINAL REPORT.**

**Plugging of the well bore.
Liability under bond is retained
until surface restoration,
environmental remediation and
final inspection is completed.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Tina Huerta TITLE Regulatory Compliance Supervisor DATE January 4, 2007

Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471

For State Use Only

APPROVED BY: Gerry Guye TITLE Deputy Field Inspector DATE JAN 12 2007

Conditions of Approval (if any)

District II - Artesia