District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 June 1, 2004

MAR 13 2007

and production facilities, submit to NMOCD District Office.

Wistream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan"? Yes \(\sum \) No \(\sum \)

Type of action: Registration of a pit or below-grade tank \(\sum \) Closure of a pit or below-grade tank \(\sum \) OCD - ARTESIA, NA Telephone: 605) 373-5905 Operator: Menbourne Oil Co. e-mail address: Address: Box 5270 , Hobbs NM 81241 Facility or well name: Pience Cossing 36 St. #1 API #: 30-015-33467 U/L or Qtr/Qtr D Sec 36 Longitude W/03 '54' 37.9" NAD: 1927 ☐ 1983 ☐ County: Eddu Surface Owner: Federal State Private Indian Below-grade tank Type: Drilling Production Disposal Volume: ____bbi Type of fluid: Workover Emergency Construction material: Lined Unlined Double-walled, with leak detection? Yes If not, explain why not. Liner type: Synthetic Markness /2 mil Clay Pit Volume (20 points) Less than 50 feet Depth to ground water (vertical distance from bottom of pit to seasonal 50 feet or more, but less than 100 feet (10 points) 0 high water elevation of ground water.) 100 feet or more (0 points) Yes (20 points) Wellhead protection area: (Less than 200 feet from a private domestic 0 No (0 points) water source, or less than 1000 feet from all other water sources.) Less than 200 feet (20 points) Distance to surface water: (horizontal distance to all wetlands, playas, 200 feet or more, but less than 1000 feet (10 points) irrigation canals, ditches, and perennial and ephemeral watercourses.) 0 1000 feet or more (0 points) Ranking Score (Total Points) Ŏ If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if NIA your are burying in place) onsite 💢 offsite 🔲 If offsite, name of facility____ . (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No 🜠 Yes 🔲 If yes, show depth below ground surface__ ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavation Attached Pit Losure Additional Comments: I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines K, a general permit 🔲, or an (attached) alternative OCD-approved plan 🔲. Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of his responsibility for compliance with any other federal, state, or local laws and/or regulations. Approval;
Printed Name/Title Semilar Signature

Visibilet II Segresviese Date: 3/13/07

P.O. Box 310 Hobbs, NM 88241-0310

New Mexic Environmental Services

Hobbs. New Mexico Off 505,392,8584 Cell 505.631.2442 Fax 505.392.3085

Hobbs, New Mexico

Reserve Pit Remediation

SURFACE PIT CLOSURE PLAN

PIT PARAMETERS

COMPANY: Mewbourne Oil Co.

WELL SITE: Pierce Crossing 36 State #1

LEGAL DESCRIPTION: Unit D Sec 36 T24s R29e, 830

FNL 845 FWL, Eddy co.

The reserve pit inset on this leasehold is being permitted to close as per New Mexico OCD "Pit and Below Grade Tank Guidelines" dated November 1, 2004.

This pit was excavated and formed to the dimensions roughly 150' X 150' X 6' deep. A 12 mil membrane liner and pad was used to prevent leakage to the surface soils. A visual examination of the membrane liner indicates that the liner had maintained its integrity.

After the drilling and completion phase of this project, the water phase of the pit contents were pumped and hauled to an approved water injection facility. It is estimated that the volume of solids remaining are to +/- 1800 yards. The burial cell is to be excavated and lined with a minimum 12 mil membrane that complies with ASTM Standards: D-5747, D-5199, D-5994, and D-4833. The cuttings will be loaded as to allow for > 36" freeboard to ground level. After the cuttings are loaded the 12 mil liner will be folded over the top, and a 20 mil minimum thickness liner meeting the minimum requirements as outlined in ASTM Standard Methods: D-5747, D-5199, D-5994, D-4833; will be used to cap and cover to an extended area that exceeds three feet in all directions from the

edge of the burial cell. This cap will be constructed as to slope and allow for water runoff from burial cell.

A minimum of 36" of top soil will be used to cover the burial cell. This soil must be capable of supporting plant growth. A seed mixture will be used as to conform to local BLM and OCD requirements.

After the drilling solids are buried, the natural contour of the surrounding soils will be mechanically shaped as to prevent erosion of the well site until vegetation is established.

LOCATION DIAGRAM

Mewbourne Oil, Pierce Crossing 36 State #1 API #30-015-33469 V-DOOR Northwest

