Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office May 27, 2004 Energy, Minerals and Natural Resources District h 1625-N/French Dr., Hobbs NM.88240 WELL API NO. District II 30-015-26469 OIL CONSERVATION DIVISION 1301 W. Grand Ave , Artesia, 5. Indicate Type of Lease District III 1220 South St. Francis Dr. STATE FEE 🖂 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH Jenny Com PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well Other P&A JUN 29 2007 2. Name of Operator 9. OGRID Number Yates Petroleum Corporation OCD-AKIL 025575 3. Address of Operator 10. Pool name or Wildcat 105 S. 4th Street, Artesia, NM 88210 Wildcat; Wolfcamp 4. Well Location E : 1750 feet from the North line and 660 Unit Letter feet from the West line 17 Range Township 19S **NMPM** Section 25E Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3543'GR Pit or Below-grade Tank Application or Closure Pit type ______ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _ Pit Liner Thickness: Below-Grade Tank: Volume _bbls; Construction Material _ 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK , \square ALTERING CASING □ TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS.□ PLUG AND ABANDON PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 6/21/07 – Cleaned out hole to 6303'. Tagged top of liner. 6/22/07 - RIH to top of liner. Could not get through, Called NMOCD and OK'd spotting plug. Spotted 40 sx cement at 7425'. WOC. Tagged at 7170'. NMOCD approved.

6/25/07 – Set a CIBP at 3966'. Tagged CIBP. Spotted 25 sx cement. PUH to 5480' and spotted 25 sx cement. Set a CIBP at 4680'. 6/26/07 – Tagged CIBP. Circulated plugging mud. Spotted 40 sx cement, combined 2 plugs. Spotted 25 sx cement at 2027'. Spotted 25 sx cement at 1242'. WOC. Tagged at 1098'. 6/27/07 – Circulated 20 sx cement from 98' to surface. Cut off wellhead. Installed dry hole marker. WELL IS PLUGGED AND ABANDONED. FINAL REPORT.	
	Plugging of the well bore. Liability under bond is retained until surface restoration, environmental remediation and final inspection is completed.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan. SIGNATURE TITLE Regulatory Compliance Supervisor DATE June 28, 2007	
Type or print name Tina Huerta E-mail address	s: <u>tinah@ypcnm.com</u> Telephone No. <u>505-748-1471</u>
For State Use Only APPROVED BY: Conditions of Approval (if any)	Gerry Guye Deputy Field Inspector District II - Artesia DATE JUL 1 1 2007