

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUL 18 2007  
OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☒ Final Report

Name of Company Devon Energy	Contact Tommy Polly
Address 2401 Pecos Ave, Artesia, NM 88210	Telephone No. 505-748-5290
Facility Name Ore Ida SWD Battery	Facility Type SWD Battery

Surface Owner	Mineral Owner Devon Energy	Lease No. API: 30-015-29290
---------------	----------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section 14	Township 24S	Range 29E	Feet from the 1780	North/South Line FSL	Feet from the 860	East/West Line FEL	County EDDY
-------------	------------	--------------	-----------	--------------------	----------------------	-------------------	--------------------	-------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release PRODUCED WATER	Volume of Release 22 BBLS	Volume Recovered 22 BBLS
Source of Release WATER TANK	Date and Hour of Occurrence 7/12/07, 09:00	Date and Hour of Discovery 7/12/07, 10:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? GERRY GUYE	
By Whom? TOMMY POLLY	Date and Hour 11 00 AM 7/12/2007	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

ELECTRICITY APPARENTLY WENT OUT, SWD PUMP WAS DOWN, ALARM DID NOT WORK. SWD TANK RAN OVER. ALL PRODUCED WATER STAYED INSIDE OF FIREWALL WHICH IS LINED; ALL WATER WAS RECOVERED. ALL ELECTRICITY RESTORED AND ALARMS FIXED.

Describe Area Affected and Cleanup Action Taken.\*

ALL PRODUCED WATER STAYED INSIDE FIREWALL WHICH IS LINED. VACUUM TRUCK PICKED UP ALL WATER

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: TOMMY POLLY 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: TOMMY POLLY	Approved by District Supervisor: 	
Title: ASST FOREMAN	Approval Date: JUL 23 2007	Expiration Date:
E-mail Address: tommy.polly@dmn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/12/2007	Phone: 505-748-5290	

\* Attach Additional Sheets If Necessary