

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: <u>ROSS ROBINSON OIL INC</u>	Contact: <u>ROSS ROBINSON</u>
Address: <u>Box 1929</u>	Telephone No.: <u>505-631-4691</u>
Facility Name: <u>ST HL 2 #2</u>	Facility Type: <u>Pumping well</u>

Surface Owner: <u>TURKEY TRACK RANCH</u>	Mineral Owner: <u>ROBINSON OIL INC</u>	Lease No.: <u>30-015-28070</u> <u>A-9739-19</u>
--	--	--

LOCATION OF RELEASE

Unit Letter: <u>E</u>	Section: <u>2</u>	Township: <u>19 South</u>	Range: <u>29 E</u>	Feet from the: <u>1650</u>	North/South Line: <u>North</u>	Feet from the: <u>330</u>	East/West Line: <u>West</u>	County: <u>Eddy</u>
-----------------------	-------------------	---------------------------	--------------------	----------------------------	--------------------------------	---------------------------	-----------------------------	---------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: <u>STUFFING BOX LEAK</u>	Volume of Release: <u>10 BBLs</u>	Volume Recovered: <u>0</u>
Source of Release:	Date and Hour of Occurrence:	Date and Hour of Discovery:
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Well Pump Gas hooked, Burns Packing
Tighten Packing vent Gas to get pump action back

Describe Area Affected and Cleanup Action Taken.*

12x12 Area Around well head and pump area 50 ft x 4 ft
Dug out affected area, Hauled soil off, replaced with catclike from location

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Ross L Robinson Jr.</u>		OIL CONSERVATION DIVISION	
Printed Name: <u>Ross L Robinson Jr.</u>		Approved by District Supervisor: <u>[Signature]</u>	
Title: <u>Pres.</u>		Approval Date: <u>8/21/2007</u>	Expiration Date:
E-mail Address: <u>mrj2001@yahoo.com</u>		Conditions of Approval:	Attached <input type="checkbox"/>
Date: <u>8-18-07</u>	Phone: <u>505-631-4691</u>		

* Attach Additional Sheets If Necessary