

Summary Report

Tom Brandt
Marshall & Winston Inc.
P.O. Box 50880
Midland, Tx, 79710

Report Date: December 12, 2007

Work Order: 7121022



Project Location: Eddy County, NM
Project Name: Dublin Federal 23-4

30-015-35730

Sample	Description	Matrix	Date Taken	Time Taken	Date Received
144966	Main Pit Wall/Floor resample @ 20' N 1/2	soil	2007-12-04	14:00	2007-12-10
144967	Main Pit Wall/Floor resample @ 20' S 1/2	soil	2007-12-04	14:30	2007-12-10

Sample: 144966 - Main Pit Wall/Floor resample @ 20' N 1/2

Param	Flag	Result	Units	RL
Chloride		96.9	mg/Kg	5.00

Sample: 144967 - Main Pit Wall/Floor resample @ 20' S 1/2

Param	Flag	Result	Units	RL
Chloride		177	mg/Kg	5.00