

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 11 2008
OCD-ARTESIA

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-015-27178

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company, LP	Contact <input type="checkbox"/> Jerry Mathews
Address P. O. Box 250, Artesia, NM 88210	Telephone No. <input type="checkbox"/> (505) 748-5234
Facility Name North Pure Gold 9-1	Facility Type <input type="checkbox"/> Oil Well

Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/> NM-77046
---------------	---------------	---

LOCATION OF RELEASE

Unit Letter	Section 9	Township 023S	Range 031E	Feet from the 330	North/South Line South	Feet from the 1980	East/West Line West	County Eddy
-------------	--------------	------------------	---------------	----------------------	---------------------------	-----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release Water Spill	Volume of Release 84 bbls	Volume Recovered <input type="checkbox"/> 6 bbls
Source of Release Valve on water tank	Date and Hour of Occurrence 9-8-07 9:15 AM	Date and Hour of Discovery <input type="checkbox"/> 9-8-07 9:15 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Don Mayberry 9:20 AM	
By Whom? <input type="checkbox"/>	Date and Hour <input type="checkbox"/>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Truck driver closed intake valve on water tank and left it closed, therefore, causing the tank to run over. Spill was contained in dike.

Describe Area Affected and Cleanup Action Taken.*

Sent soil samples and letter of intent to Gerry Guye on 10/5/07. His letter back to us is attached along with all the information from the contractor of what they were requested to do by Mr. Guye

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Mathews</i>	OIL CONSERVATION DIVISION	
Printed Name: Jerry Mathews	Approved by <input type="checkbox"/> District Supervisor: <i>Gerry Guye</i>	
Title: Completion Foreman	Approval Date: JAN 15 2008	Expiration Date.
Date: January 10, 2008	Phone 505-748-5234	Conditions of Approval: <i>CLOSED</i>
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-