Jim Hollan

432-563-1166

p. 4

District 1 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesla, NM 88210
District III
1000 Rio Brezos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

14591 Release Notification and Corrective Action													
30 015 29387						OPERATOR							
Name of Company: Merit Energy Company						Contact: Jackey Williams							
Address: P.O. Box 69, Loco Hills N.M., 88255						Telephone No.: 505-677-2327							
Facility Name: Turner B 132 (flow line)						Facility Type: Flow line							
Surface Owner: BLM Mineral Owner:						r: BLM Lease No.: LC-029395-B							
LOCATION OF RELEASE													
Unit Letter B	Section 20	Township 17S	Range 31E	Feet from the	North	/South Line North	Feet from the 2421		t/West Line County East Eddy				
	L		atitude	32.82716401	L	Longitud	te 103.8912	606		L			
NATURE OF RELEASE													
Type of Rele	ase: Produ	ced fluids		, 1231	Volume of Release: ~200 bbls Volume Recovered: ~120								
Source of Release: Flow line							lour of Occurrence	Date and Hour of Discovery:					
						1/29/08 unknown 1/29/08 4:30							
Was Immediate Notice Given? ☑ Yes ☐ No ☐ Not Require						If YES, To Whom? Jim Amos (BLM) & Mike Bratcher (OCD)							
By Whom? Jim Hollon						Date and Hour: 1/30/07 11:45							
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*													
Describe Cause of Problem and Remedial Action Taken.* Rupture in flow line. Bad section of line was cut out and replaced.													
Describe Area Affected and Cleanup Action Taken,*													
The fluids ran from the leak in the flow line through depressions in the sand-hills to a flat area north of Marbob's tank battery. Vacuum trucks were													
summoned to recover the free liquids, totaling approximately 120 bbls. The grossly affected soils are being scraped up and hauled to a nearby OCD approved land farm. One calls are being made before additional excavation / delineation can be performed.													
I hereby certif	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other													
federal, state, or local laws and/or regulations.													
A .						OIL CONSERVATION DIVISION							
Signature:	les !	Fill	s		1								
Printed Name: Jackey Williams						Approved by District Supervisor: T. Gum by SB							
Title: Area Fo	xeman				P	pproval Date	2-6-08	1	xpiration [
E-mail Address:						Conditions of Approval: REMEDIATION Attached							
Date: 1-30-0		Yest		one: 575-677-232	7	PIA	N DUE	3-1	0-08				
Attach Additi			٠										
nseb	0803	72.591	5				_			21	LP.	-123	