



ALLSTATE ENVIRONMENTAL SERVICES, LLC



P.O BOX 11322
MIDLAND, TEXAS 79702
OFFICE: (432) 682-3547
FAX: (432) 682-4182
Contractors License #94195

FEB 19 2008
OCD-ARTESIA

February 4, 2008

New Mexico Oil Conservation Division
District 2
1301 Grand Avenue
Artesia, New Mexico 88210

30-015-35346

Dear Sir/Ma'am

Included in this mailing is the closure report for OGX Resources Buckshot St. Com #1 in Eddy County, New Mexico. As indicated in the summary the pit closure work began January 05, 2008 and was completed on January 22, 2008.

Any concern or questions regarding this site may be addressed to Paula Guell, Office Supervisor, Allstate Environmental Services, at 432-682-3547, or e-mail paula@basinbroadband.com or the company e-mail address at allstate@basinbroadband.com

Sincerely,

Paula Guell
Office Supervisor
Allstate Environmental Services, LLC

Cc: OGX Resources, T.X.
Allstate Environmental Services - file

Accepted for record
NMOCD
FEB 22 2008

An Environmental Company
SOLIDIFICATION, BIOREMEDIATION, LAND FARMING, SOIL SHREDDING

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87503

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 03 2008
OCD-ARTESIA

Form C-144
June 1, 2004

For drilling and production facilities, submit to appropriate NMOCD District Office
For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure

Is pit or below-grade tank covered by a "general plan" Yes No X

Type of action: Registration of a pit or below-grade tank Closure of a pit or below-grade tank XX

Operator: OGX Resources, LLC Telephone: 432 684-6381 e-mail address: ann.ritchie@wtor.net	
Address: c/o Box 953, Midland, TX 79702 35346	
Facility or well name: Backshot State Com, Well #1 API #: 30.015-35270 U/L or O/L or Q/L Sec 31 T74S R28E	
County: Pecos Latitude: 32.1019.1 Longitude: 104.0720.2 NAD: 1927 X 1983	
Surface Owner: Federal State X Private Indian ☐	
Type: Drilling Production ☐ Disposal ☐ Workover ☐ Emergency ☐ Lined X Unlined ☐ Liner type: Synthetic X Thickness 20 mil Clay ☐ Pit Volume: 4800	Below-grade tank Volume: ___ bbl Type of fluid: ___ Construction material: ___ Double-walled, with leak detection? Yes ☐ If not, explain why not: ___
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet (20 points) 50 feet or more, but less than 100 feet (10 points) 100 feet or more (0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes (20 points) No X (0 points)
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet (20 points) 200 feet or more, but less than 1000 feet (10 points) 1000 feet or more X (0 points)
Standing Volume (Total Volume) 0 20 POINTS	

If this is a pit closure: (1) Attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if you are burying in place) onsite ☐ offsite ☐ If offsite, name of facility: ___ (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No X Yes ☐ If yes, show depth below ground surface ___ ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations.

Additional Comments: Pit Closure: Drilling pit will be deep burial in separate pit lined with 42 mil plastic and topped with 20 mil liner, 3" below surface to. Allow fresh dirt to be SOLIDIFICATION MESHES, CURED MIXED 3001 WITH DRILL CUTTINGS BURIED IN A 12" LINED PIT WITH A 20 MIL CAP AND 3 FT OF TOP SOIL. PITS WILL BE FILLED WITH CLEAN DIRT AND CONTAINED TO MATCH THE AREA.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X a general permit ☐, or an (attached) alternative OCD-approved plan ☐.

Date 1-2-08

Printed Name/Title Ann E. Ritchie

Signature

Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.

Approval

Signature

Signed By

Jan 03 2008

JAN 03 2008

NOTIFY OCD 24 HOURS PRIOR to beginning closure and 24 HOURS PRIOR to obtaining samples. Samples are to be obtained from pit area and analyses submitted to OCD prior to back-filling.

If burial trench is to be constructed in pit area, samples are to be obtained and analyses submitted to OCD PRIOR to lining trench.

2 d

8541 289 516


801M

Jan 02 21 03:40P

5053652851

Page 1

OGX Resources
Buck Shot State #1
Eddy County New Mexico
Begin Date 01/05/08 end Date 01/22/08





PHONE (575) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR
ALLSTATE (OGX)
ATTN: CHARLES CHANLEY
P.O. BOX 11322
MIDLAND, TX 79702
FAX TO: (432) 682-4182

Receiving Date: 01/22/08
Reporting Date: 01/22/08
Project Owner: OGX
Project Name: NOT GIVEN
Project Location: BUCK SHOT STATE #1

Analysis Date: 01/22/08
Sampling Date: 01/21/08
Sample Type: SOIL
Sample Condition: COOL & INTACT
Sample Received By: ML
Analyzed By: KS

LAB NO.	SAMPLE ID	Cl ⁻ (mg/kg)
H14122-1	N/E	144
H14122-2	S/E	96
H14122-3	CENTER	144
Quality Control		500
True Value QC		500
% Recovery		100
Relative Percent Difference		< 0.1

METHOD: Standard Methods 4500-ClB

Note: Analyses performed on 1:4 w:v aqueous extracts.

Kristin Superior
Chemist

01/22/08
Date

H14122 OGX

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



ARDINAL LABORATORIES

101 East Marland, Hobbs, NM 88240 2111 Beechwood, Abilene, TX 79603

(505) 393-2326 FAX (505) 393-2476 (325) 873-7001 FAX (325) 873-7020

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

[illegible]