

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG - 4 2008
OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

1 SEB0821756052
1 SEB0821755825

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	OXY USA	Contact	Kelton Beard
Address	102 S Main Carlsbad, NM 88220	Telephone No. (O)	505-887-8337 C) 575-390-1903
Facility Name	Federal NEF #3 SWD	Facility Type	Disposal Well

Surface Owner	BLM	Mineral Owner		Lease No.	
---------------	-----	---------------	--	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	25	22S	31E					Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	+1000 bbls	Volume Recovered	2bbls
Source of Release	Flow line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	7-30-08 / 1:00pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD- Gerry Guye; BLM- Jim Amos		
By Whom?	Kelton Beard- Oxy HES Specialist	Date and Hour	See above		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Corrosion caused a hole in the steel injection line causing produced water to leak onto the pasture. A vac-truck was called to remove all standing fluids

Describe Area Affected and Cleanup Action Taken.*

The area affected is approx. 30,000 sq. feet in the pasture. Depth of contamination is unknown. Delineation will take place to determine the extent of the contamination and a work plan will be worked up and submitted to the BLM and NMOCD for approval.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Kelton Beard	Approved by District Supervisor: 		
Title: HES Specialist	Approval Date: 8-4-08	Expiration Date:	
E-mail Address: kelton_beard@oxy.com	Conditions of Approval:		Attached <input checked="" type="checkbox"/>
Date: 7-31-08			2RP-205

* Attach Additional Sheets If Necessary

SEB0821756142