

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

AUG 15 2008
OCD-ARTESIA
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Read & Stevens, Inc 13917	Contact	William Palmer
Address	PO Box 1719, Lovington, NM 88260	Telephone No.	575.396.5391
Facility Name	Marbob State #2	Facility Type	producing well and tank battery

Surface Owner	State of NM	Mineral Owner	State of NM	Lease No.
---------------	-------------	---------------	-------------	-----------

3001533570

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	19	19S	29E	660'	South	660	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	oil	Volume of Release	24 bbls	Volume Recovered	10 bbls
Source of Release	tankage on location	Date and Hour of Occurrence	3.9.08 between 0600 - 1300 hours	Date and Hour of Discovery	3.9.08 1300 hours
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mr. Mike Bratcher, OCD - Artesia		
By Whom?	William Palmer	Date and Hour	3.10.08 - 1300 hours		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Tank repairs and interior coating completed.

Describe Area Affected and Cleanup Action Taken.*

The area surrounding the tank battery pad is predominately sand. Soil samples were taken at the tank battery, 50', 100' and 200' away to the southeast. An additional sample was taken in a slightly affected area to the southwest of the tank battery. All samples indicated acceptable TPH and chloride levels. (see attached)

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: William V. Palmer	Approved by District Supervisor: 		
Title: Superintendent	Approval Date: 8-27-08	Expiration Date: N/A	
E-mail Address: wpalmer@read-stevens.com	Conditions of Approval: N/A		Attached <input type="checkbox"/> N/A
Date: August 12, 2008	Phone: 575.396.5391		

* Attach Additional Sheets If Necessary
cc: wellfile

2RP-149