

District I - (505) 393-6161  
P O. Box 1980  
Hobbs, NM 88241-1980  
District II - (505) 748-1283  
1301 W Grand Ave  
Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Road  
Aztec, NM 87410  
District IV - (505) 827-7131

**State of New Mexico**  
**Energy Mineral and Natural Resources Department**  
**Oil Conservation Division**  
**1220 South St. Francis Drive**  
**Santa Fe, New Mexico 87505**  
**(505) 476-3440**

AUG 26 2008  
OCD-ARTESIA

**Form C-141**  
Originated 2/13/97

Submit 2 copies to  
Appropriate District  
Office in accordance  
with Rule 116 on  
back side of form

Release Notification and Corrective Action

**OPERATOR**

☐ Initial Report

☒ Final Report

Name Marathon Oil Company 14021	Contact Jerry Harrison
Address P.O 1324 Artesia, NM 88211	Telephone No 575-457-2621 ext. 121
Facility Name Indian Basin Field	Facility Type Gas well

Surface Owner BLM	Mineral Owner BLM	Lease No. Indian Federal Gas Com. #1
----------------------	----------------------	---

**LOCATION OF RELEASE**

Unit Letter	Section 19	Township 21S	Range 24E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

**NATURE OF RELEASE**

Type of Release produced water	Volume of Release 14.2921	Volume Recovered 10		
Source of Release tank	Date of Occurrence 08/11/08	Hour of Occurrence 1:00 PM	Date of Discovery 08/11/08	Hour of Discovery 3:30 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A			
By Whom? N/A	Date of Notification 01/00/00		Hour of Notification 12:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A			

If a watercourse was Impacted, Describe Fully (Attach Additional Sheets If Necessary)

N/A



Describe Cause of Problem and Remedial Action Taken (Attach Additional Sheets if Necessary)

A one inch nipple failed, due to corrosion, resulting in tank fluids emptying into dike. The field operator shut in the well. The spilled fluids were vacuumed up. The tank will be replaced.

Describe Area Affected and Cleanup Action Taken (Attach Additional Sheets if Necessary)

Transport driver pulled spilled water from the diked area. All produced water stayed within the dike.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature 	<b>OIL CONSERVATION DIVISION</b> <b>TIM GUM</b> <b>by MB</b>	
Printed Name J. Harrison	Approved by District Supervisor 	Approval Date: 8/27/08
Title Filed Supervisor	Expiration Date: N/A	Attached <input type="checkbox"/>
Date 8/19/08	Phone (505) 457-2621	Conditions of Approval N/A