

District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG - 7 2008
OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

SEB0826651154
N 3680520050355

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Arena Resources Inc 220420	Contact: Tony Tucker
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-602-8601
Facility Name: NBQU #16	Facility Type: Injection Well

Surface Owner: BLM	Mineral Owner: BLM	Lease No. 33129
--------------------	--------------------	-----------------

30-015-10087

LOCATION OF RELEASE

Unit Letter J	Section 28	Township 18S	Range 30E	Feet from the 1743	North/South Line SL	Feet from the 784	East/West Line EL	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------------------	----------------------	----------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 125 BBLS	Volume Recovered: 0
Source of Release: Ruptured Injection Line	Date and Hour of Occurrence: 7-29-08 8:00 pm	Date and Hour of Discovery: 7-29-08 11:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Injection line ruptured. Will excavate, sample and dispose.

Describe Area Affected and Cleanup Action Taken.*

Location and pasture land. Water soaked into the sand.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Tony Tucker	Approved by District Supervisor: 	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Title: Production Foreman	Approval Date: 9.22.08	Expiration Date: 11-24-08
E-mail Address: ttucker@arenaresourcesinc.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/> LRP-226
Date: 8-4-08	Phone: 575-738-1739	

* Attach Additional Sheets If Necessary

SEB0826651254

SEE ATTACHED
STIPULATIONS