

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised June 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: OXY USA, Inc.	Contact: Mark Andersen
Address: 6 Desta Drive, Suite 6000, Midland, TX 79705	Telephone No. (432) 685-5824
Facility Name: Dimaggio Tank Battery	Facility Type: Well

Surface Owner	Mineral Owner	Lease No. NM-1800
---------------	---------------	-------------------

30-015-26930

#### LOCATION OF RELEASE

Unit Letter J	Section 16	Township 26S	Range 29E	Feet from the 1650'	North/South Line South	Feet from the 1693'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32° 02' 24.2N Longitude 103° 59' 10.9W

#### NATURE OF RELEASE

Type of Release Oil	Volume of Release 40 bbls	Volume Recovered 35 bbls
Source of Release Tank Battery	Date and Hour of Occurrence 12-7-07 11:45 AM	Date and Hour of Discovery 12-7-07 @ 11:45 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - Terry Gregston, NMOCD - Gerry Guye	
By Whom? Johnny Burnett	Date and Hour 12-7-07 12:15 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

Oil production being produced to oil tank, tank filled up and equalizing line plugged up and allowed 40 barrels of oil to overflow.

Describe Area Affected and Cleanup Action Taken \*

Vacuum truck was called and recovered 35 barrels of oil. Backhoe was utilized to pick up and remove saturated soil. Highlander (Tetra Tech) collected samples from excavation for evaluation. Impacted soils were excavated and hauled to disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tim Reed (Tetra Tech, Agent for OXY)	Approved by District Supervisor: 	
Title: Sr. Project Manager	Approval Date: 10-1-08	Expiration Date: N/A
E-mail Address: timothy.reed@tetratech.com	Conditions of Approval: N/A	Attached <input type="checkbox"/> N/A
Date: 8/5/08 Phone: (432) 682-4559		

\* Attach Additional Sheets If Necessary

2RP-136