

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

SEB0828238785  
NSEB0828238644

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation	Contact	Brandi Barthels
Address	P. O. Box 1559, Midland, TX 79702	Telephone No.	361-935-9377
Facility Name	Elliot #1	Facility Type	

Surface Owner	P	Mineral Owner		Lease No.	
---------------	---	---------------	--	-----------	--

30 015 21655

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	28	18S	30E	2310	FNL	990	FWL	Eddy

Latitude 32.43.19.42 Longitude 103.58 56.46

NATURE OF RELEASE

Type of Release	saltwater	Volume of Release	20bbls	Volume Recovered	10bbls
Source of Release	Rumaldo	Date and Hour of Occurrence	09/25/08 11:00a.m.	Date and Hour of Discovery	09/25/08 a.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Rumaldo called Brandi		
By Whom?	Brandi Barthels	Date and Hour	09/25/08 11:00 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

N/A



Describe Cause of Problem and Remedial Action Taken.\*

Saltwater leak outside surface pump. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.\*

The affected area of soil is 100' x 30'. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date
Printed Name: Brandi Barthels	Approved by District Supervisor: 	Approval Date: <u>10-8-08</u>	Expiration Date: <u>12-8-08</u>
Title: Regulatory & Environmental Affairs Manager	Conditions of Approval:		Attached <input checked="" type="checkbox"/>
E-mail Address: bbarthels@plateenergy.com	Date: 10-03-08 Phone: 361.935.9377		Within 30 days, on or before <u>11-8-08</u> , completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage

\* Attach Additional Sheets If Necessary

SEB 0828238935

2RP - 242

Notify OCD 48 hours prior to  
obtaining samples where analyses  
are to be presented to OCD