

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

SEP - 5 2008
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form
OCD-ARTESIA

Release Notification and Corrective Action

SEB0827648200
nSEB0827647882

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation 236183	Contact	Brandi Barthels
Address	P.O. Box 1559, Midland, TX 79702-1559	Telephone No.	1-361-935-9377
Facility Name	Hudson State 001	Facility Type	Oil

Surface Owner State	Mineral Owner State	Lease No.	B-2179
---------------------	---------------------	-----------	--------

30 015 24007

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	9	17S	28E	2310	South	660	East	Eddy

Latitude 32.847444 Longitude -104.174369

NATURE OF RELEASE

Type of Release	Saltwater	Volume of Release	18-20 bbl	Volume Recovered	5 bbl
Source of Release	Water Tank	Date and Hour of Occurrence	08/13/08 approx. 2:00 PM	Date and Hour of Discovery	08/13/08 @3:20 p.m.
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Hole in tank bottom of water tank. Water was immediately transferred to another tank. Soil sampling will be conducted and remedial action plan will be developed and executed.

Describe Area Affected and Cleanup Action Taken.*

The affected area was approximate 20' x 30'. Cleanup action taken included a vacuum truck which came on site immediately to recover the saltwater. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Brandi Barthels

Printed Name: Brandi Barthels

Approved by District Supervisor:

TGum by SB

Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.

Title: Regulatory & Environmental Affairs Manager

Approval Date: 10-2-08

Expiration Date: 12-8-08

E-mail Address: bbarthels@platenergy.com

Conditions of Approval:

Within 30 days, on or before 11-8-08, completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage

Attached ☒

2RP - 232

Date: 08/26/2008 Phone: 361.935.9377

* Attach Additional Sheets If Necessary

SEB 0827648415