

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCT 01 2008

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD-ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

2008 SEP 26 PM 2:18

Release Notification and Corrective Action

ISEB0828237975
nSEB0828237732

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation	Contact	Brandi Barthels
Address	P. O. Box 1559, Midland, TX 79702	Telephone No.	361-935-9377
Facility Name	Magnolia Battery	Facility Type	Battery

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

30 C1525373

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
X N	XS 6	X 193	28E	330	South	2160	West	Chavez Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	oil	Volume of Release	131 BBLS	Volume Recovered	40 BBLS
Source of Release	corrosion	Date and Hour of Occurrence	09/22/08 @ 2:00 p.m.	Date and Hour of Discovery	09/22/08 @ 2:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Paul Evans @ BLM, Mike McGhee @ BLM, Mike Bratcher @ NMOCD			
By Whom?	Brandi Barthels	Date and Hour 09/22/08 6:20 p.m.			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

N/A



Describe Cause of Problem and Remedial Action Taken.*

Bottom of tank blew out due to corrosion. The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.*

The spill covered an area of approximately 158'x107'. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brandi Barthels	Approved by District Supervisor: 	Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.
Title: Regulatory & Environmental Affairs Manager	Approval Date: 10-08-08	Expiration Date: 12-08-08
E-mail Address: bbarthels@platenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 09/23/08	Phone: 361.935.9377	

* Attach Additional Sheets If Necessary

SEB0828238045

Within 30 days, on or before 11-08-08, completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage.

2RP - 241
Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD