

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

2008 SEP 11 PM 2 36

Release Notification and Corrective Action

ISE00827630929
NSE00827630658

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Tandem Energy Corporation 236183	Contact	Brandi Barthels
Address	P.O. Box 1559, Midland, TX 79702	Telephone No.	361-935-9377
Facility Name	South Lucky Lake Queen Unit 001	Facility Type	oil

SEP 19 2008

OCD-ARTESIA

Surface Owner	S	Mineral Owner		Lease No.	1
---------------	---	---------------	--	-----------	---

30 005 60360

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	16	15S	29E	330	South	990	East	Chaves

Latitude 33.009307 Longitude 104.027846

NATURE OF RELEASE

Type of Release	Oil and Saltwater	Volume of Release	16 bbl	Volume Recovered	0
Source of Release	Nipple on Check Valve	Date and Hour of Occurrence	08/26/08 @ 11:00 a.m.	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

¼ " nipple broke on check valve causing 6 bbls of oil and 10 bbls of saltwater to be spilled. Nothing was recovered.

The remedial action plan will be developed and executed for the site after soil sampling is conducted.

Describe Area Affected and Cleanup Action Taken.*

The affected area was approximate 30' x 30'. The remediation plan will be developed and executed based upon the soil analysis results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Brandi Barthels*

Printed Name: Brandi Barthels

Title: Regulatory & Environmental Affairs Manager

E-mail Address: bbarthels@platenergy.com

Date 09/08/2008 Phone: 361.935.9377

OIL CONSERVATION DIVISION

Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date.

Approved by District Supervisor: *T. Gumbly*

Approval Date: 10-2-2008

Expiration Date: 12-2-2008

Conditions of Approval:

Attached ☒

Within 30 days, on or before 11-3-08, completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage.

2RP - 230

Notify OCD 48 hours prior to obtaining samples where analyses are to be presented to OCD

* Attach Additional Sheets If Necessary

SE00827631085