

District I
1625 N French Dr, Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCT 20 2008
OCD-ARTESIA

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-015-10254

OPERATOR

☐ Initial Report ☐ Final Report

Name of Company SANDLOTT ENERGY	Contact JACKIE BREWER
Address P.O BOX 711 LOVINGTON NM 88260	Telephone No. 575-631-4592
Facility Name RESLER YATES # 317	Facility Type ACTIVE PRODUCTION WELLHEAD

Surface Owner NMSLO	Mineral Owner	Lease No.30-015-10254
---------------------	---------------	-----------------------

LOCATION OF RELEASE

Unit Letter F	Section 21	Township 18S	Range 28E	Feet from the 1650	North/South Line NORTH	Feet from the 1650	East/West Line WEST	County EDDY
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release HISTORICAL	Volume of Release N/A	Volume Recovered N/A
Source of Release ACCUMULATED RELEASE FROM ACTIVE WH	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NOT APPLICABLE


Describe Cause of Problem and Remedial Action Taken.*

WELL HEAD LEAK AT STUFFING BOX LESS THAN 5BBLs 3FT BY 3FT RADIUS

Describe Area Affected and Cleanup Action Taken.*

DUG AROUND WELLHEAD 3FT BY 6FT RADIUS APPROX. 3FT IN DEPTH HAULED SOIL TO CRI REFILLED WITH CLEAN SOIL

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Jackie Brewer	Approved by District Supervisor:		
Title: Operator	Approval Date:	Expiration Date:	
E-mail Address: Brewer212@AGL.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10-14-08	Phone: 631-4592		

* Attach Additional Sheets If Necessary

Accepted for record
NMOCD



OCT 22 2008