

OCT 23 2008

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

OCD-ARTESIA

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report☒ Final Report

Name of Company <i>Kersey &amp; Co</i>	Contact <i>Ken Wade</i>
Address <i>P.O. Box 1248, Fredericksburg Tx 78624</i>	Telephone No. <i>830 992-9588</i>
Facility Name <i>Parry Federal #1</i>	Facility Type <i>Oil Well</i>
Surface Owner <i>BLM</i>	Mineral Owner <i>BLM</i>
Lease No. <i>LC067348A</i>	

## LOCATION OF RELEASE

Unit Letter <i>J</i>	Section <i>28</i>	Township <i>18S</i>	Range <i>29E</i>	Feet from the <i>2310</i>	North/South Line <i>2310</i>	Feet from the <i>2310</i>	East/West Line <i>2310</i>	County <i>Eddy</i>
-------------------------	----------------------	------------------------	---------------------	------------------------------	---------------------------------	------------------------------	-------------------------------	-----------------------

## NATURE OF RELEASE

Type of Release <i>Oil</i>	Volume of Release	Volume Recovered
Source of Release <i>Leak from stuffing box</i>	Date and Hour of Occurrence	Date and Hour of Discovery
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Describe Area Affected and Cleanup Action Taken.\*

*Contaminated soil was hauled to land farm. Area around well bore was excavated to a depth of 10-12 ft and a 3 ft thick cap of concrete was poured with remaining cavity filled with caliche. All excavated area was filled with caliche and a 2 ft. dike was formed around the tank battery.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature <i>Kenneth R Wade</i>	Approved by <i>TEMBY</i>	
Printed Name: <i>Kenneth R Wade</i>	District Supervisor: <i>SB</i>	
Title: <i>Manager</i>	Approval Date: <i>11-6-08</i>	Expiration Date: <i>N/A</i>
Date: <i>10-16-08</i>	Phone: <i>830 992-9588</i>	Conditions of Approval: <i>N/A</i>
		Attached <input type="checkbox"/> <i>N/A</i>

\* Attach Additional Sheets If Necessary

2 RP-177