Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

UCD-AKTESIA

FORM APPROVED OMB No 1004-0135 Expires July 31, 1996



5. Lease Serial No.

NMNM 048344

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.					3	
SUBMIT IN TRIPLICATE – Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well		40				
X Oil Well Gas Well	Other NUV	19 2008			8. Well Nam	e and No.
2. Name of Operator	ana	A Farmer	⊕ D ⊃		P	URE FEDERAL #4
LIME ROCK RESOURCES	A, L.P.	-ARTE	Sia _		9. API Well	No.
a. Address c/o Mike Pippin L	LC	3b. Phone	No. (mclud	e area code)		30-015-36097
		505-327-	505-327-4573		10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Red Lake, Queen-Grayburg-San Andres 51300	
990' FNL & 2310' FEL Unit B					AND	
Sec. 21, T17S, R28E					Eddy County, New Mexico	
12. CHECK APPROPRIATE BO	X(ES) TO INDICATE NA	TURE OF N	OTICE, RI	EPORT, OR O	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	,	Production	(Start/Resume)	Water Shut-Off
	Alter Casing	Fracture		Reclamati	` ,	☐ Well Integrity
Subsequent Report	Casing Repair	☐ New Co	onstruction	Recomplet	te	Other Change of Operator
Final Abandonment Notice	Change Plans Convert to Injection	☐ Plug an ☐ Plug Ba	nd Abandon ack	☐ Temporari	ily Abandon posal	
Attach the Bond under which the work Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspe	andonment Notices shall be filed	in a multiple com	file with BLM/ mpletion or rea	completion in a ne	bsequent reports sh w interval, a Form	all be filed within 30 days 3160-4 shall be filed once
Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspective 7/1/08. Lime Rock Street, Suite 4600, Houston	erations if the operation results is andonment Notices shall be filed scrion) Resources A. L.P. be, TX 77002. Lime Ros	in a multiple con only after all r ecame the ck obtaine	operator	BIA. Required sus- completion in a nevoluding reclamation or this well. I from SDX	bequent reports st w interval, a Form , have been comp Lime Rock Resources	all be filed within 30 days 3160-4 shall be filed once sletted, and the operator has 's address is 111 Bagby Inc. PO Box 5061, Midland.
Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspective 7/1/08. Lime Rock Street, Suite 4600, Houston	erations if the operation results is andonment Notices shall be filed scrion) Resources A. L.P. be, TX 77002. Lime Ros	in a multiple con only after all r ecame the ck obtaine	operator	BIA. Required sus- completion in a nevoluding reclamation or this well. I from SDX	bequent reports st w interval, a Form , have been comp Lime Rock Resources	all be filed within 30 days 3160-4 shall be filed once sleted, and the operator has
Following completion of the involved op Testing has been completed. Final Abdetermined that the site is ready for final inspection of the involved option option of the involved option optio	erations if the operation results is andonment Notices shall be filed scrion) Resources A. L.P. be, TX 77002. Lime Ros	in a multiple con only after all r ecame the ck obtained K Resource	operator	BIA. Required sus- completion in a nevoluding reclamation or this well. I from SDX	bequent reports st w interval, a Form , have been comp Lime Rock Resources	all be filed within 30 days 3160-4 shall be filed once sletted, and the operator has 's address is 111 Bagby Inc. PO Box 5061, Midland.
Following completion of the involved op Testing has been completed. Final Abdetermined that the site is ready for final inspection of the final inspec	erations if the operation results is andonment Notices shall be filed scrion) Resources A. L.P. be, TX 77002. Lime Ros	in a multiple con only after all r ecame the ck obtaine	operator	BIA. Required sus- completion in a nevoluding reclamation or this well. I from SDX	bequent reports st w interval, a Form , have been comp Lime Rock Resources	all be filed within 30 days 3160-4 shall be filed once sleted, and the operator has 's address is 111 Bagby Inc. PO Box 5061. Midland. CEPTED FOR RECORD
Following completion of the involved op Testing has been completed. Final Abdetermined that the site is ready for final inspection of the final inspection of the final inspection of the final inspection. Final inspection of the final inspection o	erations if the operation results is andonment Notices shall be filed scrion) Resources A. L.P. be, TX 77002. Lime Ros	in a multiple con only after all r ecame the ck obtained K Resource	operator	BIA. Required sus- completion in a nevoluding reclamation or this well. I from SDX	beguent reports st w interval, a Form, have been comp Lime Rock Resources ACC	all be filed within 30 days 3160-4 shall be filed once sleted, and the operator has sleted, and the operator has sleted, and the operator has considered. Po Box 5061. Midland. CEPTED FOR RECORD
Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspective 7/1/08. Lime Rock Street, Suite 4600, Houston TX 79704. The BLM bond in the site is ready for final inspection.	erations If the operation results is andonment Notices shall be filed scrion.) Resources A. L.P. be TX 77002. Lime Roman Roman Roman Roman Roman Rock	in a multiple con only after all r ecame the ck obtained K Resource	operator	BIA. Required sus- completion in a nevoluding reclamation or this well. I from SDX	bequent reports st w interval, a Form, have been comp Lime Rock Resources ACC	all be filed within 30 days 3160-4 shall be filed once sleted, and the operator has sleted, and the ope
Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspective 7/1/08. Lime Rock Street, Suite 4600. Houston TX 79704. The BLM bond in the site is ready for final inspection.	erations If the operation results is andonment Notices shall be filed scrion.) Resources A. L.P. be TX 77002. Lime Roman Roman Roman Roman Roman Rock	in a multiple coronly after all recame the ck obtained Resource	operator	BIA. Required sus- completion in a nevoluding reclamation or this well. I from SDX	bequent reports st w interval, a Form, have been comp Lime Rock Resources ACC	all be filed within 30 days 3160-4 shall be filed once sleted, and the operator has sleted, and the ope
Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspective 7/1/08. Lime Rock Street, Suite 4600. Houston TX 79704. The BLM bond in the site is ready for final inspection.	erations If the operation results is andonment Notices shall be filed action.) Resources A. L.P. be TX 77002. Lime Romanmer for Lime Rock	in a multiple con only after all r ecame the ck obtained K Resource	operator	BIA. Required sus- completion in a new reduding reclamation or this well. I from SDX 8 00499.	bequent reports star interval, a Form, have been comp Lime Rock Resources ACC Gerry NMO	all be filed within 30 days 3160.4 shall be filed once sletted, and the operator has sletted, an
Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspective 7/1/08. Lime Rock Street, Suite 4600. Houston TX 79704. The BLM bond in TX 79704. The BLM bond in TX 79704. The BLM bond in TX 79704.	erations If the operation results is andonment Notices shall be filed scrion.) Resources A. L.P. be TX 77002. Lime Roman Roman Roman Roman Roman Rock	in a multiple coronly after all recame the ck obtained Resource	operator	BIA. Required succompletion in a new completion in a new clouding reclamation or this well. I from SDX 8 00499.	beguent reports st w interval, a Form, have been comp Lime Rock Resources ACC Gerry NMOO	all be filed within 30 days 3160.4 shall be filed once sletted, and the operator has sletted, an
Following completion of the involved op Testing has been completed. Final Ab determined that the site is ready for final inspective 7/1/08. Lime Rock Street, Suite 4600. Houston TX 79704. The BLM bond in TX 79704.	restions If the operation results is andonment Notices shall be filed action) Resources A. L.P. be, TX 77002. Lime Romumber for Lime Rock is true and correct	in a multiple coronly after all recame the ck obtained Resource	operator d this we	BIA. Required succompletion in a new clouding reclamation or this well. I from SDX 3 00499. Petrolei	bequent reports star interval, a Form, have been comp Lime Rock Resources ACC Gerry NMO	all be filed within 30 days 3160.4 shall be filed once sletted, and the operator has sletted, an
Following completion of the involved op Testing has been completed. Final Abdetermined that the site is ready for final inspections of the site is ready for final inspection. Effective 7/1/08. Lime Rock Street, Suite 4600. Houston TX 79704. The BLM bond in TX 79704. The BLM bond in Name (Printed/Typed) Mike Signature Multiple Signature Street Stre	restions If the operation results is andonment Notices shall be filed action) Resources A. L.P. be, TX 77002. Lime Romumber for Lime Rock is true and correct	in a multiple coronly after all recommends the ck obtained Resource	operator d this we	BIA. Required succompletion in a new completion in a new clouding reclamation or this well. I from SDX 8 00499.	beguent reports st w interval, a Form, have been comp Lime Rock Resources ACC Gerry NMOO	all be filed within 30 days 3160.4 shall be filed once sletted, and the operator has sletted, an
Following completion of the involved op Testing has been completed. Final Abdetermined that the site is ready for final inspection of the site is ready for final inspection. Final material inspection of the site is ready for final inspection. Final material inspection of the site is ready for final inspection. Final material inspection of the site is ready for final inspection. Final material inspection. Effective 7/1/08. Lime Rock Street, Suite 4600, Houston TX 79704. The BLM bond is signature. Mike Signature Approved by Conditions of approval, if any, we attached the signature attached the signature of the signature attached the signature of the signature attached the signature of the signature attached the signature attached the signature of the signature attached the signature of the signature attached the signature attached the signature of the signature attached the signature attached the signature of the signature attached the signature att	Resources A, L.P. be TX 77002. Lime Rock This spa	Title CE FOR FEI T warrant or 100 only after all r	ile with BLM/mpletion or re- mpletion or re- m	BIA. Required succompletion in a new clouding reclamation or this well. I from SDX 3 00499. Petrolei	beguent reports star interval, a Form, have been complete, have be	all be filed within 30 days 3160-4 shall be filed once sletted, and the operator has sletted, an
Following completion of the involved op Testing has been completed. Final Abdetermined that the site is ready for final inspection. Effective 7/1/08. Lime Rock Street, Suite 4600, Houston TX 79704. The BLM bond in the site is ready for final inspection. I hereby certify that the foregoing Name (Printed/Typed) Mike	Resources A, L.P. be TX 77002. Lime Rock This spa This spa This spa This spa This spa This spa Taylor of this notice does not table title to those rights in the set operations thereon.	ramultiple coronly after all recame the ck obtained Resource Resource Title Date CE FOR FEI t warrant or threat lease Ingly and willful	operator d this welles is NME	Petrolei Petrolei No	Lime Rock Resources ACC Gerry NMO um Enginee	Is address is 111 Bagby Inc. PO Box 5061. Midland. CEPTED FOR RECORD NOV 19 2008 Guye, Deputy Field Inspector (Agent) 1008