

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

DEC 8 2008  
OCD-ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

NAME <u>0835030121</u>		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company COG OPERATING LLC <u>229/37</u>		Contact Robyn Odom			
Address 550 W. Texas, Suite 1300 Midland, TX 79701		Telephone No. 432-685-4385			
Facility Name - Red Lake Sand Unit #45		Facility Type- Battery			
Surface Owner State		Mineral Owner		Lease No. API# 30-015-33198	

LOCATION OF RELEASE

Unit Letter P	Section 20	Township 17S	Range 28E	Feet from the 990	North/South Line South	Feet from the 990	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.8150641048197 Longitude -104.19250

NATURE OF RELEASE

Type of Release- Water/oil	Volume of Release- 2 bbls	Volume Recovered- none
Source of Release- Valve leaked	Date and Hour of Occurrence- 11/21/08- 10:30am	Date and Hour of Discovery 11/21/08- 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher	
By Whom? Kimberly Wilson	Date and Hour 11/21/08 10:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Pinhole size leak at valve. Valve repaired

Describe Area Affected and Cleanup Action Taken.\*

This was a very small spill. A valve leaked spraying oil and water which began pooling on the ground and flowing west off the location then south into a field. 2' X 15'. We removed all saturated/contaminated soil and will then haul to a land fill. Replace soil with clean back fill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Robyn Odom</u>		OIL CONSERVATION DIVISION	
Printed Name: Robyn Odom		Approved by District Supervisor: <u>T. Camacho by SB</u>	
Title: Agent		Approval Date: <u>12-15-08</u>	Expiration Date: <u>1-15-09</u>
E-mail Address: rododom@conchoresources.com		Conditions of Approval:	
Date: 12/05/08 Phone: 432-685-4385		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

KMW0833629394

Submit Final C141 with  
Supporting documentation by