

DEC 152008

DATE_

Submit 2 Copies To Appropriate District Office	State of New Mexico	UUU-ARIESIA	Form C-103	
District I	Energy, Minerals and Natural Resources		October 25, 2007	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	.07	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION OIL CONSERVATION DIVISION		30.015.3668.7 5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		FEE 🖵	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease 1		
1220 S. St. Francis Dr., Santa Fe, NM	,			
SUNDRY NOTICE	S AND REPORTS ON WELLS	7. Lease Name or Unit Ag	reement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Ecase Name of Onit Ag		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		toster tee 3	toster tee 31 com	
PROPOSALS) 1. Type of Well: Gas Well Other		8. Well Number		
2. Name of Operator		9. OGRID Number		
Nearburg Producing Company		0.5	142	
3. Address of Operator		10. Pool name or Wildcat		
3300 N A St., Bldg 2, Ste 120, Midland, TX 79707		Undesignate	$d:(\lambda)C_{\bullet}$	
4. Well Location		- CA - 3 - 5 CA	4) 000	
Unit Letter $\overline{J}: \cancel{980}$ feet from the \underline{S} line and $\cancel{980}$ feet from the $\underline{\mathcal{E}}$ line				
Section 31 Township 195 Range 25C NMPM County Eddy				
	1. Elevation (Show whether DR, RKB, RT, GR, e			
	3544		**************************************	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
	_			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			NG CASING 🔲 '	
TEMPORARILY ABANDON			A Ц	
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEME	:N1 JOB 🔲		
OTHER:	☐ ☐ Location is	ready for OCD inspection af	ter P&A	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as no	early as possible to original ground contour and h	as been cleared of all wark, tras	h, flow lines and	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all park, trash, flow has and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				
All other environmental concerns have been addressed as per OCD rules.				
	abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have bee	n removed from	
non-retrieved flow lines and pipelines.			i i	
W/lean all results have 1.4	and the Country design of the Country of the Countr	and a distance of the second s	41	
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one				
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.				
SIGNATURE LIP TITLE KIGHT DATE KINDS				
16 Tordo - Airodo D Li ma				
TYPE OR PRINT NAME 5 50000 E-MAIL: Sjordan Prear bing com PHONE: 432/186-5835				
For State Use Only	_	•	,	

TITLE

APPROVED BY:
Conditions of Approval (if anv):