

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Mesquite SWD Inc.	Contact Clay L Wilson
Address P.O. Box 1479 Carlsbad NM 88221	Telephone No. 505-706-1840
Facility Name Exxon State	Facility Type SWD
EXXON STATE OCS	
Surface Owner BLM	Mineral Owner State
Lease No.	

LOCATION OF RELEASE

Unit Letter 0	S 16 15	Township 21S	Range 27E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	-------------

Latitude _____ Longitude _____

30 015 22055

NATURE OF RELEASE

Type of Release Salt Water	Volume of Release 1200 BBL	Volume Recovered 1180 BBL
Source of Release Line broke on back of 500 bbl tank	Date and Hour of Occurrence 12/23/08 9:00am	Date and Hour of Discovery 12/23/08 11:00am
Was Immediate Notice Given? Required X <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not	If YES, To Whom? OCD Artesia office Gerry Guye	
By Whom? Clay L Wilson	Date and Hour 12/23/08 11:30am	
Was a Watercourse Reached? <input type="checkbox"/> Yes X <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
12-23-08 8inch line broke on the back of tank ,shut off valves replaced line with a new line.

Describe Area Affected and Cleanup Action Taken.*
Inside fire wall we had 40Mill under tanks, 12-23-08 Called in vacuum trucks and vacuum up all the produce water.10BBL ran over fire wall down bar ditch pick up all contaminated soil with back hoe and haul to CRI.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Clay L Wilson	Approved by District Supervisor: 	
Title: President	Approval Date: 1-2-09	Expiration Date: N/A
E-mail Address: claywilson@pccnm.com	Conditions of Approval:	
Date: 12-24-2008 1840	Phone: 575-706-1840	Attached <input type="checkbox"/> N/A