Submit 3 Copies To Appropriate District	State of New Me	xico	FEB - 2 2009	Form C-103
Office -	Energy, Minerals and Natural Resources			May 27, 2004
<u>District I</u> 1625 N French Dr , Hobbs, NM 88240			WELL API NO.	
District II	OH CONCEDIATION DIVICION		30-015-29590	
1301 W Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	Chara Chara
<u>District III</u> 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr.			FEE 🗌 😂
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease 1	No.
1220 S St Francis Dr., Santa Fe, NM 87505				
	ES AND REPORTS ON WELLS		7. Lease Name or Unit Ag	reement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Barclay State	·
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			8. Well Number	
PROPOSALS)			2	
1. Type of Well: Oil Well Gas Well Other				
2. Name of Operator			9. OGRID Number	
Forest Oil Corporation 3. Address of Operator			10. Pool name or Wildcat	
707 17 th Street, Suite 3600, Denver, Colorado			Livingston Ridge South (Delaware)	
			Elvingston Ridge South (1	
4. Well Location				
Unit Letter:Jfeet fr	om the <u>1980</u> line and _			
Section 2 Township 23S Range 31E NMPM County Eddy				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4189 GR				
Pit or Below-grade Tank Application or Closure				
Pit typeDepth to Groundwat	erDistance from nearest fresh w	ater well Dist	ance from nearest surface water_	
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				NG CASING 🗌
TEMPORARILY ABANDON				
PULL OR ALTER CASING				
OTHER:		OTHER: Rod I	Repair⊠	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.				
0				
12-11-08 – RUPU, POH to 7/8" body break 125 down				
12-12-08 – RIH w/fishing tool, had trouble getting over fish, caught fish & unseated pmp. POH w/pmp. Found 4-3/4 rods & 3 1 ½				
sinkerbars bent.				
12-15-08 – Pick up pmp and 3 new k-bars 1 ½ and replace 4-3/4 rods, RBIH, load tbg w/30 bbls wtr, press to 500 psi held good, long				
stroke, good pmp action. RU PU clean location ACCEPTED FOR RECORD				
ACCEPTED FOR RESOLD				
	1		i	
→ (EEB 0 3 2009				
	Garey	Cuye, Deputy Field !	Inspector, c	
I hereby certify that the information al	pove is true and complete to the books of the condition of the condition to NMOCD guidelines in the condition of the conditio	CD-District i A	and belief. I further certify to the latternative OCD	hat any pit or below-
	+	, ' '	1	approved plane.
SIGNATURE DATE 1-27-09				
Type or print name Cindy Bush E-mail address: cabush@forestoil.com Telephone No. 303-812-1554				
For State Use Only	C			
ADDDOVED rodo DDHI114			,	
APPROVED rods, RBIH load tbg w// BY:	דודו ב		DATE	
Conditions of Approval (if any):	TITLE		DATE	-
Conditions of Approval (if ally).				