

RECEIVED SEP 25 2009

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-35260

Release Notification and Corrective Action

7MLB0926841742

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company - Corkran Energy	243452	Contact - Dennis Corkran
Address - 300 Beardsley Lane C204 Austin, TX 78746		Telephone No. - 512-329-6140
Facility Name - Orleans 25 #1		Facility Type - Drilling Pit
Surface Owner - Private	Mineral Owner -	Lease No. 30-015-35260

LOCATION OF RELEASE



Unit Letter B	Section 25	Township 18S	Range 26E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32° 43.444' N Longitude 104° 19.923' W

NATURE OF RELEASE

Type of Release - Drilling Pit Contents	Volume of Release - N/A	Volume Recovered - N/A
Source of Release - Drilling Pit	Date and Hour of Occurrence NA	Date and Hour of Discovery 9-24-09
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Drilling pit contents leaked into underlying soil.		
Describe Area Affected and Cleanup Action Taken.* Pit bottoms were tested and delineated to NMOCD standards. Attached is the initial plat map and field analytical of the delineation. Confirmation samples were sent to a third party lab. Remediation plan is to excavate all impacted soil at the following areas: TP1, TP2, TP3 and TP4 will be excavated to 10' bgs and TP5 will be excavated to 20' bgs. The impacted soil will be excavated and hauled to Lea Land Disposal. The site will be backfilled and seeded per the original pit closure plan. A final report will be sent with the Final C-144 once the pit closure is complete.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Logan Anderson	Approved by District Supervisor: 	
Title: Consultant	Approval Date: SEP 25 2009	Expiration Date:
E-mail Address: la_elkeenv@yahoo.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9-24-09	Phone: 432-366-0043	

* Attach Additional Sheets If Necessary

REMEDATION per OCD Rules and
Guidelines. SUBMIT REMEDIATION
PROPOSAL BY: N/A Plan is on C-141

2RP-343

7MLB0927249013