8 2009 OCT

DATE 10/9/09

NMOCD ARTESIA Submit One Copy To Appropriate District State of New Mexico Form C-103 Office March 18, 2009 Energy, Minerals and Natural Resources District I WELL API NO. 1625 N. French Dr , Hobbs, NM 88240 District II 30-015-21736 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE X FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A EMPIRE ABO UNIT "I" DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 271 1. Type of Well: X Oil Well Gas Well Other 2. Name of Operator 9. OGRID Number BP AMERICA PRODUCTION COMPANY 00778 3. Address of Operator 10. Pool name or Wildcat P.O. BOX 1089, EUNICE NM 88231 EMPIRE ABO 4. Well Location Unit Letter B: 670 feet from the N line and 1700 feet from the E line Township 18S Range 28E NMPM County EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3654' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON | REMEDIAL WORK ALTERING CASING □ TEMPORARILY ABANDON CHANGE PLANS \Box COMMENCE DRILLING OPNS.□ P AND A \Box PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB □ Location is ready for OCD inspection after P&A OTHER: All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE. The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. [X] If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.) All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from nonretrieved flow lines and pipelines. When all work has been completed, return this form to the appropriate District office to schedule an inspection. SIGNATURE (Xanu TITLE: Area Operations Team Lead DATE: 10/7/09 TYPE OR PRINT NAME: Barry C. Price E-MAIL: barry.price@bp.com PHONE: 575-394-1648 For State Use Only TITLE OF to Polace

APPROVED BY:

Conditions of Approval (if any):