

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 30 2009

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

XX ☐ Initial Report ☐ Final Report

Name of Company	Basic Energy Services, LP 246368	Contact	DAVID ALVARADO
Address	P.O. BOX 10460 MIDLAND TX 79702	Telephone No.	575.746.9667
Facility Name	STATE G COM #1	Facility Type	SWD

Surface Owner	Mineral Owner	Lease No.	3001522955
---------------	---------------	-----------	------------

30-015-22955

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	24	19S	27E	1980	NORTH	660	WEST	EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	CRUDE OIL	Volume of Release	5 BBLS	Volume Recovered	3 BBLS
Source of Release	LOAD LINE OFF 210 BBL TANK	Date and Hour of Occurrence	9-28-09 or 9-28-09	Date and Hour of Discovery	8:30 AM 9/28/09
Was Immediate Notice Given?	xxx <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Yard Supervisor	Ruben Trujillo Loco Hills	
By Whom?	Pumper Richard Pena	Date and Hour	9-28-09 8:30 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes xxx <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	None		

If a Watercourse was Impacted, Describe Fully.*

No impact

Describe Cause of Problem and Remedial Action Taken.*

Out side load valve failed and tank valve was leaking.
Call was made to Supervisor and authorities were notified on possible vandalism or theft. On arrival supervisor determined faulty valves and replaced them.

Both valves were replaced.

Describe Area Affected and Cleanup Action Taken.*

North side of dike ran to west side next to the dike where it gathered at the lowest spot 15' by 20'


Vacuum truck was used to recover 3 bbls and was taken to CRI

Back hole was used to scrape oiled soil and it also was taken to CRI total of 12 yards per Supervisor.

Received call from Sherry at OCD at 4:00pm about NMSP reporting spill. On arrival, location and been cleaned and back dragged.

Call OCD at 5:00pm. Called OCD on 9-29-09 left msg. to talk to Sherry.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the MOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 

OIL CONSERVATION DIVISION

Printed Name: <u>David H Alvarado</u>		Approved by District Supervisor: <u>RD by SD</u>		Remediation Actions to be completed and Final C-141 submitted with confirmation analyses/documentation on or before the Expiration Date
Title: <u>Area Mgr</u>		Approval Date: <u>10-26-09</u> Expiration Date: <u>12-26-09</u>		
E-mail Address: <u>david.alvarado@BasicEnergyServices.com</u>		Conditions of Approval:		Attached <input checked="" type="checkbox"/> <u>JRA 353</u>
Date: <u>9-29-09</u> Phone: <u>575.746.9663</u>		<u>STIPULATIONS</u>		

* Attach Additional Sheets If Necessary

ISEB0929952477
 NSEB0929952551
 SEB0929952777