

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Mcwbourne Oil Company 14744	Contact Manny Ortega
Address 701 S. Cecil, Hobbs, NM 88241	Telephone No. 575-390-4111
Facility Name State JL 36 Battery 001	Facility Type Oil separation facility
Surface Owner Mcwbourne Oil Company	Mineral Owner Mcwbourne Oil Company
Lease No. 001	

30-015-23428

LOCATION OF RELEASE

Unit Letter O	Section 36	Township 18S	Range 29E	Feet from the 660'	South Line	Feet from the 1980'	East Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------	------------------------	-----------	----------------

Latitude 33 Longitude 102

NATURE OF RELEASE

Type of Release Spill	Volume of Release 4 bbls	Volume Recovered 4 bbls
Source of Release Oil separator flow line	Date and Hour of Occurrence 11/26/09 hour unknown	Date and Hour of Discovery 11/27/09 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Darold Gray	
By Whom? An anonymous phone call was made.	Date and Hour November 27 th , 2009, 8:00 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully *



Describe Cause of Problem and Remedial Action Taken. *

Battery was vandalized (valve was removed from the flow line to heater). Visually impacted soil was excavated and taken to CRJ.

Describe Area Affected and Cleanup Action Taken. *

Mcwbourne is in the process of delineation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCED rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCED marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCED acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Manny Ortega		Approved by District Supervisor: 	
Title: Engineer		Approval Date: 12-14-09	Expiration Date: 2-19-09
E-mail Address: Mortega@mewbourne.com		Conditions of Approval:	
Date: 12-11-09	Phone: 575-390-4111	Within 30 days, on or before JAN. 14, 2010, completion of a remediation work plan based on delineation should be finalized and submitted for approval to the Division summarizing all actions taken and/or to be taken to mitigate environmental damage.	
		Attached <input checked="" type="checkbox"/>	

* Attach Additional Sheets If Necessary

ISEB0934827467
ISEB0934829961
SEB0934830337

Notify OCD 48 hours prior to
obtaining samples where analyses
are to be presented to OCD