District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr, Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

	The second secon	
	RECENT	-
	RECEIVED	Form C-141
S	\$	Revised October 10, 2003
	DEC - 7 2009 Distri	10
	Submit .	4 Copies to appropriate
- [	Alasoo Distri	of Office in accordance
L	NMOCD ARTESIA	with Rule 116 on back
	MITESIA	side of form

20	015		7 /	_	$\overline{}$
<i>3</i> 0-	Urs	٠.	ء د	_	_

## Release Notification and Corrective Action

nMLB09365-37176				OPERATOR			Initial Report  Final Repo						
Name of Company OXY USA /6686				Contact Kelton Beaird									
Address 1502 W. Commerce Carlsbad, NM 88220						Telephone No. (O) 575-628-4100							
Facility Name Two Marks CTB						Facility Type Central Tank Battery							
Surface Owner BLM Mineral Owner					)wner				Lease	No. 300153	3622		
				LOCA	TIO	N OF REI	FASE			_			
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
•				i			-						
M	36	21S	24E		L					Eddy			
			La	titude	<del> </del>	Longitud	le	**********					
				NAT	URE	OF RELI	EASE						
Type of Rele							Release 20bbls			Recovered			
Source of Re	lease Vent	line				Date and Hour of Occurrence Date and Hour of Discovery 11-24-09 @ 10:00am							
Was Immedi	ate Notice (	Given?				If YES, To	Whom?		11-24-07	(a) 10.00am			
			Yes 🔲	No 🛛 Not Re	quired								
By Whom?							our See above						
Was a Water	course Read	ched?	Yes 🛭	l No		If YES, Vo	lume Impacting th	he Water	course.				
IC Water						<u> </u>							
If a watercot	arse was im	pacted, Descri	ibe rully.										
			•										
Describe Cau	se of Proble	em and Remed	lial Action	n Taken.*		-							
				g the P.W. in the v	essel to	overflow out	of the vent line.						
Describe Are	a Affected a	and Cleanup A	ction Tak	en.*		<del></del>							
Area affected	was on the	location apro	x. 80' X 3	0'. A vac-truck w		ed to pick up a	ıll standing fluid r	emaining	g on locat	ion. Delinea	tion wi	Il occur and	
a clean-up pla	an will be si	ubmitted to the	e BLM and	d NMOCD for app	proval.								
T.1 -1	C 11 1 1 1 1					1		<u> </u>		777.6			
							knowledge and un d perform correct						
							rked as "Final Re						
should their o	perations ha	ave failed to a	dequately	investigate and re	mediate	contamination	on that pose a threa	at to gro	und water	, surface wa	er, hur	nan health	
		ddition, NMO vs and/or regu		tance of a C-141 r	eport do	oes not relieve	the operator of re	esponsib	ility for c	ompliance w	ith any	other	
reactar, state,	or local lay	A A	garous.	<del>-/-)</del>			OIL CONS	ERVA	TION	DIVISIO	N		
0:	7/ . /		`	·	.		3-2-31				<u></u>		
Signature:	1. 1.			#			service at the	1 1					
Printed Name: Kelton Beaird				Approved by District Supplies Branches									
Title: HES S	pecialist				A	Approval Date	DEC 3 1 200	9 <sub>Ex</sub>	piration l	Date AN &	1 2	010	
E-mail Addre	ss: kelton_	beaird@oxy.co	om			Conditions of	Approval:			Attached			
Date: 11-30-09						DEL 450115			1	1 2 5	_		
Attach Additional Sheets If Necessary					 	REMEDIATION per OCD Rules and							
Guideli					idelines. SUBMIT REMEDIATION  OPENSAL BY (13/10)								
ישנוששטוקיי	2/4/0				PRC	<u> POSAL BY:</u>	1/31/10	····	· · · · · ·			011	