




DCP Midstream
10 Desta Dr. Suite 400 W
Midland, TX 79705
O: (432) 620-4207
F: (432) 620-4162



March 13, 2010

State of New Mexico Oil Conservation Division

Region II

via certified mail 7008 3230 0001 9244 8209

Attn: L. Randy Dade

1301 W. Grand Ave.

Artesia, New Mexico 88210

**RE: Monthly AGI Readings
Artesia Gas Plant Gas Injection Well
API No. 30-015-32324**

To Whom it May Concern:

Enclosed are monthly readings for the Acid Gas Injection well at Artesia Gas Plant for the month of February 2010. These are being submitted on a monthly basis due to the request by the OCD in lieu of the requirement to perform a yearly mechanical integrity test on the well. DCP Midstream LP (DCPM) understands that we will be required to perform a mechanical integrity test on the well once every five years.

DCPM performed the Mechanical Integrity Test (MIT) on September 9, 2008 and the results are filed at the facility.

If you have any questions about this information, feel free to contact me at (432) 620-4207 or via email at jdbebbington@dcpmidstream.com.

Respectfully,

DCP Midstream, LP

Jon D. Bebbington

Sr. Environmental Specialist

Cc: Artesia Facility File 3.3.4
Corporate File 3.3.4
Regional Env. File 3.3.4

DAY OF MONTH	PT-6185 WELLHEAD PRESS PSIG	PT-6188 INNER CASING PRESS PSIG	PT-6189 OUTER CASING PRESS PSIG	FQI-6101 ACID GAS FLOW TO COMPRESSOR MSCFD
1	1771	138	91	772
2	1773	130	90	801
3	1843	128	89	801
4	1784	124	90	813
5	1786	138	93	811
6	1789	139	93	809
7	1789	128	91	802
8	1786	124	89	772
9	1784	107	87	825
10	1787	101	88	886
11	1801	116	92	876
12	1798	124	93	879
13	1799	136	95	836
14	1799	124	93	840
15	1794	124	92	797
16	1797	141	92	658
17	1786	146	91	659
18	1789	156	96	771
19	1793	153	98	790
20	1796	158	99	802
21	1797	151	97	787
22	1795	144	96	782
23	1788	111	89	778
24	1790	136	91	659
25	1790	129	94	843
26	1795	121	93	821
27	1797	129	95	813
28	1801	128	95	830

MONTHLY AVG 1793

132

93

MONTHLY TOTAL22314
