

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED  
Budget Bureau No 1004-0137  
Expires: March 31, 2007

5. Lease Serial No.  
LC024171C

6. If Indian, Allotted or Tribe Name

7. If Unit or CA Agreement, Name and for Pit

8. Well Name and No.  
Keys Federal C #3

9. API Well No.  
30-015-04676

10. Field and Pool, or Exploratory Area  
PCA; Yates

11. County or Parish, State  
Eddy Co., NM

**SUBMIT IN TRIPLICATE – Other instructions on reverse side.**

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Shackelford Oil Co.

3a. Address  
3510 N. A St. Bldg B Suite 100, Midland, TX 79705

3b. Phone No. (include area code)  
432-682-9784

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
1980' FSL & 1980' FEL, Sec. 15, T-20S, R30E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input checked="" type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be Filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

Location has been cleaned.

"REJECTED" See Attached

J. C. Morris  
3-21-10

14 I hereby certify that the foregoing is true and correct  
Name (Printed/Typed) Debbie McKelvey Title Agent  
Signature *Debbie McKelvey* Date 2/5/10

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States and false, Fictitious or fraudulent statements or representations as to any matter within its jurisdiction

RI 3/24/2010

NMLC024171C; Keys Federal C #3  
1980' FSL & 1980' FEL, Sec. 15, T20S-R30E  
Eddy County, New Mexico

RE: Reclamation Shortfalls

The Sundry Notice (Form 3160-5) dated 2/5/10 was rejected for the following reasons: Need to remove the power poles and associated electrical lines, poly flow lines, anchors and posts, and other debris on the location. Need to remove all historical spills on the access road, and two spills running to the west and the southwest. All soils and brush pushed to the sides of the location for plugging operations are to be spread across the location. The brush will make good mulch. Contour the location to blend with the surrounding landscape, and is to be ripped and the location seeded with BLM seed mixture #2. The access road is to be turned into a two-tract ranch road. Contact Jim Amos @ 575-234-5909 if any questions. Submit a Sundry Notice showing Subsequent Report of Reclamation when the work is completed. Work is to be completed within 6 months of plugging operations (6/21/10).